

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	12/10/2019	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Wachtman-Schroeder, Inc.	
Facility Name:	Whitetail Stuart Lease	
Facility Physical Location:	36.785215, -96.268172 (SE Sect. 30, T 27N, R 10E)	
(city, state, zip code)	Pawhuska, Oklahoma 74056	
Mailing address:	P.O. Box 1138	
(city, state, zip code)	Pawhuska, Oklahoma 74056	
County/Parish:	Osage County	
Facility Phone Number	702-303-7954	
Facility Contact:	Mike Wachtman	
	MAWLASVEGAS@AOL.COM	
FRS Number:	N/A	
Identification/Permit Number:	OKU000872	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		18 DEC 2019
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Wachtman-Schroeder, Inc. oil and gas facility located at latitude 36.785215 and longitude -96.268172 near Pawhuska, Oklahoma on 12/10/2019 for an unannounced inspection. There were no representatives of Wachtman-Schroeder, Inc. present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is located on the Whitetail Stuart Lease

Section II - OBSERVATIONS

I observed some older damaged surface area that had some scattered areas with no vegetation growth. I observed grass was covering about 70% of the old damage. The nearby creek was iced over during the inspection. The area was fenced in.

Section III – AREAS OF CONCERN

The surface damage from a previous documented brine spill had some lack of vegetation on it. Further evaluation of this in the spring may be needed, including potentially adding more topsoil and replanting the bare areas observed.

Section IV – FOLLOW UP

EPA will conduct a follow up inspection as needed.

Section V – LIST OF APPENDICES

N/A