

INSPECTION REPORT

Attached please find the United States Environmental Protection Agency's inspection report of your inspected facility and/or any vehicles/engines identified therein. EPA is providing this report as a matter of agency policy and will contact you again only if needed.

Without making a determination that your business or organization is a small business, EPA is also providing you with a link to this Small Business Resources Information Sheet (<https://www.epa.gov/compliance/small-business-resources-information-sheet>) which provides an array of resources to help small businesses understand and comply with federal and state environmental laws.

Inspection Information	
Inspection Date(s):	03/21/2024
EPA Region/Program Conducting Inspection:	U.S. EPA, Region 4 Air Enforcement Branch
Company Name:	Grounz 4 Divorce LLC
Facility Name:	Grounz 4 Divorce LLC
Facility Physical Location: (street address, building/unit #)	4366 Holden Road
(city, state, zip code)	Lakeland, FL 33811

Inspection Report Revision History		
Revision #	Revision Date	Reason for Revision

Inspector and Approval

Aleeka Broner

Field Inspector Name

ALEEKA BRONER

Signature

Digitally signed by ALEEKA

BRONER

Date: 2024.05.17 10:48:20 -04'00'

Date

Todd Groendyke

Name of Approving
Official

Section Chief, SAES

Title

TODD GROENDYKE

Signature

Digitally signed by TODD GROENDYKE

Date: 2024.05.17 11:44:18 -04'00'

Date

FACILITY INSPECTION WORKSHEET

General Inspection Information			
Facility Name:	Grounz 4 Divorce LLC	Inspection Date	3/21/2024
Facility Address:	4366 Holden Rd. Lakeland, FL 33811	Arrival/Departure Time	1:07 p.m. EDT 3:03 p.m. EDT
		Inspection Number/ID:	3601643859-2024
Primary Facility Representative & Title:	James Pace, General Manager	Inspector(s):	Aleeka Broner, Lorianny Rivera
Facility Contact Phone/Email:	813-428-8113 Sales@G4D.us		
Time Inspector Presented Credentials:	1:20 p.m. EDT	Compliance Assistance Materials Provided to Facility:	Small Business Resources Information Sheet, OECA Enforcement Alert, and Exhaust System Repair Guidelines Fact Sheet
Permission to Enter Facility Granted? If Yes, by whom? If No, explain.	☒ Yes ☐ No		
	Robbie Casella, Owner		
Photographer Name:	N/A	Photograph Range:	N/A
Additional Personnel Present:	N/A	Areas Discussed:	☒ CBI ☒ Equipment (OBD scanner, camera) ☐ Safety Requirements
Facility Summary:	Grounz 4 Divorce LLC, located in Lakeland FL, is an automotive service shop.		

Facility Business Activities			
Types of Services (check all that apply)		Description/Observations (types and brands of parts that are manufactured or sold, types of shop services provided, etc.)	Estimated Throughput (e.g., sales per month, installs per week)
☐	Manufactures aftermarket parts		
☒	Sells aftermarket parts	Facility indicated that they sell upgraded brakes, shocks, carburetors, water pumps, rims, headlights and FASS diesel fuel systems, advertised through social media platforms. The owner stated he previously sold nGauge tuning devices which offered vehicle performance modifications.	
☒	Service shop	The facility indicated that they perform general maintenance, fabrication, and engine repair services on diesel and gasoline engine vehicles. The facility indicated that they stopped doing performance work 6-7 years ago.	Services approximately 7 vehicles/week
☐	Fleet		
☐	Other:		

Clean Air Act Title II: Mobile Source Inspection

Personnel Interviewed			
Name	Title/Position	Contact Info. (e.g., email, phone number)	Interviewed by (Last name of Inspector)
James Pace	General Manager	813-428-8113 Sales@G4D.us	Broner

Documents Requested			
Document(s)	Status		Notes/Comments
Service invoices from October 2023 to February 2024	☒ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	Inspectors reviewed hard copies of service invoices on-site.
Receipts for parts purchased and sold by the facility from October 2023 to February 2024	☒ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	Inspectors reviewed hard copies of parts receipts on-site.
	☐ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	
	☐ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)	

Vehicles Inspected/Observed				
VIN (last 4 digits)	EPA Engine Family	Appearance of Tampering (Yes/No/TBD)	OBD Data Obtained? (Yes/No)	Observations (e.g., Who Performed Apparent Tampering?)
N/A			No	Inspectors observed the exterior of vehicles but did not photograph any vehicles.