

**Region 6 Enforcement and Compliance Assurance Division
INSPECTION REPORT**

Inspection Date(s):	10/02/2019		
Media:	Water		
Regulatory Program(s)	Brine - CWA		
Company Name:	4D Oil and Gas, LLC		
Facility Name:	Osage A SWF		
Facility Physical Location:	36.808105, -96.281125 (NE Sect. 24, T 27N, R 9E)		
(city, state, zip code)	Pawhuska, Oklahoma 74056		
Mailing address:	432 Kiheka Ave.		
(city, state, zip code)	Pawhuska, Oklahoma 74056		
County/Parish:	Osage County		
Facility Contact:	Main Office		
	918-625-7282		
FRS Number:	N/A		
Identification/Permit Number:	N/A		
Media Number:	N/A		
NAICS:	21111		
SIC:	1311		
Personnel participating in inspection:			
Kent W. Sanborn	6ECDWE	Environmental Engineer	(918) 557 – 1615
EPA Lead Inspector Signature/Date			
	Kent W. Sanborn		Date
Supervisor Signature/Date			19 NOV 2019
	Guy Tidmore		Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the 4D Oil and Gas, LLC oil and gas facility located at latitude 36.808105 and longitude -96.281125 near Pawhuska, Oklahoma on 10/02/2019 for an unannounced inspection. There were no representatives of 4D Oil and Gas, LLC present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

The facility consisted of the injection well with the EPA inventory number: OS 5571 and had an associated tank and pump.

Section II - OBSERVATIONS

I observed that the electric brine pump leaked into the secondary containment pit. I saw some surface damage west of the tank battery and well. There was about one foot of water in the pit during the inspection.

Section III – AREAS OF CONCERN

The pit had fluids in it.

Section IV – FOLLOW UP

EPA will conduct a follow up inspection in approximately 3 months.

Section V – LIST OF APPENDICES

N/A