

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	3/03/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Southwest Operating Inc. - Tyler	
Facility Name:	Pliman Lease	
Facility Physical Location:	32.896267, -95.391507	
(city, state, zip code)	Quitman, Texas 75783	
Mailing address:	727 S. Chilton	
(city, state, zip code)	Tyler, Texas 75701	
County/Parish:	Wood County	
Facility Phone Number	903-597-4279	
Facility Contact:	Main Office	
FRS Number:	N/A	
Identification/Permit Number:	TXU011254	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		APR 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Southwest Operating Inc. – Tyler oil and gas facility located near Quitman, Texas on 03/03/2020 for an unannounced inspection. There were no representatives of Southwest Operating Inc. – Tyler present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is located on the Pliman Lease. This facility has a state identification number of: RRC # 00884. The operational status of the facility was unknown at the time of the inspection.

Section II - OBSERVATIONS

I observed a drainpipe and valve in the secondary containment area. The containment area was dry, and I observed no damage outside the berms.

Section III – AREAS OF CONCERN

There was a drainpipe in the secondary containment area.

Section IV – FOLLOW UP

EPA water enforcement will refer this facility to EPA Region 6 SPCC program.

Section V – LIST OF APPENDICES

N/A