

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	2/25/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Dexxon, Inc.	
Facility Name:	Big Eagle Lease	
Facility Physical Location:	36.449247, -96.185703	
(city, state, zip code)	Hominy, Oklahoma 74035	
Mailing address:	732 E. Indiana Ave.	
(city, state, zip code)	Kiefer, Oklahoma 74041	
County/Parish:	Osage County	
Facility Phone Number	918-321-9331	
Facility Contact:	Ira E. Rongey Jr.	
FRS Number:	N/A	
Identification/Permit Number:	OKU000887	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		31 MAR 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Dexxon, Inc. oil and gas facility located near Hominy, Oklahoma on 02/25/2020 for an unannounced inspection. There were no representatives of Dexxon, Inc. present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility was located on the Big Eagle Lease and is known as the Sundown Unit. This facility was a tank battery with a deep pit.

Section II - OBSERVATIONS

I observed that the facility pit had been pumped down prior to the inspection. I saw oil staining and minor free oil in the bottom of the pit. I observed a sump pump was present at the facility. There was not a net over the pit and the pit was not lined during the inspection.

Section III – AREAS OF CONCERN

There were fluids inside the secondary containment, including oil and produced water.

Section IV – FOLLOW UP

EPA water enforcement will refer this facility to EPA Region 6 SPCC program.

Section V – LIST OF APPENDICES

N/A