

Leak Detection and Elimination Sheet

ABD00147883

Date/Time	Leak No./Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
6-10-01 2243	4787 BN	GC#1 4	5.7	South middle VCM station	0	NO	cleared next check	6-10	TC	TC
6-12-01 2110 2110	4788 BN	3 3	5.4	BOTTOM 743	0	NO	cleaning HI- mol chunk catcher	same	JO	JO
6-13-01 0624	4789 BN	GC#1 2	5.7	Could not find leak. Sag Bend	0	NO	NA	NA	NA	NA
6-15-01 1553	4790 BN	5 10	6.5	grade level 747	0	NO	cleaning dung shredders	6-15	EC	EC
6-15-01 1540 1645	4791 1645 CN	GC 5 3	7.8 8.3 6.5	SPT. 1100-802 liquid leak RG	5.0 YES	16946 YES	REPLACE LINE (absolute line)	6/18/01	MAINT	ROS
6-15-01 1229	4792 BN	GC#1 4	9.9	Faulty MPT RM McMillen	0	NO	NA	NA	NA	NA

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.
This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.