

Hooker Chemical

PLASTICS DIVISION

P O Box D

Perryville MD 21903

301 / 939 5000

TO DISTRIBUTION

FROM H E HAMMEN

DATE MARCH 6, 1981

SUBJECT WASTE TREATMENT BUILDING AND OPERATOR V/C SAMPLING

At the meeting on February 16 it was stated that the waste treatment building continues to be a problem area for vinyl exposure. In an effort to pinpoint the specific source I obtained seven (7) eight (8) hour bag samples. At the time of the meeting I was in the process of obtaining bi-weekly badge samples of Dave Brackins, plant operator. Listed below are the results.

Eight Hour Bag Samples

<u>DATE</u>	<u>AREA</u>	<u>PPM</u>
2/18/81	filter belt	5 7
2/18	work bench	1 5
2/20	vac pump sep	3 4
2/20	solut tank	2 8
2/24	Vac pmp wtr/dr	4 5
2/26	conv to trk	3 5
3/3	n e corner	3 7

Operator Badge Samples

<u>DATE</u>	<u>PPM</u>
1/27/81	76
2/7	2 7
2/10	1 8
2/12	1 9
2/16	59
2/26	57
3/3	1 4

H E Hammen

HEH/bak

Distribution

Mr D M Connor
Mr P J Eldreth
Mr H Giovannelli
Mr J R Hilt
Mr W F Tyson

OCC 014727