

Leak Detection and Elimination Sheet

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
3-3-03	6870	3		BOTTOM OF 22741	0		FOUND NOTHING			
08:18	AS	#1	6.5							
3-3-03	6871	2C#1	10.0	nothing found	0	no	nothing found			
2231	BN	5		WR			w. rollers			
3-3-03	6872	2C#1	9.2 9.0 10.0	nothing found	0	no	nothing found			
1825	BN	1		TC			TC			
3-3-03	6873	2C#1	9.1 5.7 10.0	#6 spot	0	no	tightened nut, handside off			
2151	BN	5		J.R.						
3-4-03	6874	#1	5/5/10/10				Feeding nothing in air			
2130	Ch	#1								
3-4-03	6875	#1	6.2	Not Found	No	No	NA	NA	NA	NA
0020	Ch	#8		Cleared next check						

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.
This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.