

Inspection ID	EPA Well ID#:											
	Year-Month-Day:		2	0	2	1	–	1	1	–	1	8
	EPA Permit # (or RA):											
						Page	1	Of	2			

Facility Contact Information	Facility Name:	PETRO HARVESTER OPERATING COMPANY, LLC			
	Street Address:	1107 W 6th St (office address)			
	City:	Laurel	County:	Jones	State: MS Zip: 39440
	Nature of Business:	Oil and gas extraction industry			
	Facility Owner/Operator:	PETRO HARVESTER OPERATING COMPANY, LLC		Phone:	601-651-2100
	Email:	kerry.allen@rockallenergy.com			
	Facility Contact (if different):	Kerry Allen, Sr. Operations Manager		Phone:	601-651-2105
	O/O Mailing Address:	1107 W 6th St (office address)			
City:	Laurel	County:	Jones	State: MS Zip: 39440	

Observations	Latitude (°N): <u>31.69636</u> Longitude (°W): <u>-89.14133</u> Elevation (ft): <u></u>		
	EPA GPS ID: <u>SX8123</u>	Well Status (see table): <u>AC</u>	If not Active, Reported Date Last Active: <u></u>
	Nature of Injected Fluid(s) if any: <u>Produced fluids</u>		
	General Condition of the Well Site: <u>NA</u>		

See reverse for additional observations, comments and photo log

Version 2018-04-18

CAROL CHEN

Class I and II Well Inspection Form
US Environmental Protection Agency – Region 4
Underground Injection Control Program
61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303
Phone: (404)562-9424

Inspection ID

EPA Well ID#:

2	0	2	1	–	1	1	–	1	8		

Year-Month-Day:
EPA Permit # (or RA):

--	--	--	--	--	--	--	--	--	--	--	--

Page 2 Of 2

Field Measurements and Observations (Cont.)

(Cont.) City of Laurel (COL) 6-3 #3

Team's comments on Petro Harvester's on-site operations:

We Inspected 8 wells that day, with a total of 9 people. 4 from Petro Harvester, 2 from MSOGB and 3 EPA.

All inspected wells were located in areas that were fenced and gated. All the Pumping Units and Injection Pumps were of high quality and operated almost silently. Locations seemed to be kept clean and organized.

(TA status: inactive 2 years or more. IN status: inactive less than 2 years. PBTD: Plug back total depth - not total well depth)

Photo Log

Photographer: Carl Weller EPA Camera ID: SX8123
Photo ID: 111 Time: 12:58 pm Lat (°N): 31.69636 Long (°W) -89.14124
Description: At the well site, the annulus gauge reads 425 psi. Altitude 121
Photo ID: 112 Time: 12:59 pm Lat (°N): 31.69635 Long (°W) -89.14127
Description: The tubing gauge reads 425 psi showing injection pressure. Altitude 121
Photo ID: Time: Lat (°N): Long (°W)
Description:
Photo ID: Time: Lat (°N): Long (°W)
Description:
Photo ID: Time: Lat (°N): Long (°W)
Description:
Photo ID: Time: Lat (°N): Long (°W)
Description:

Owner/Operator Representative (Optional)

Name:

Signature:

UIC Inspector

Name: Anthony Shelton

Signature:

Version 2018-04-18

Inspector Carl Weller's signature: Inspector Carol Chen's signature: CAROL CHEN

Digitally signed by CAROL CHEN
Date: 2022.01.19 13:37:23
-05'00'