

UNLOADING SLIP

Car No. CONX 9004
On Spot No. 36
Material W/L
From VC
Received 222,512
ANALYSIS

1190
OK TO UNLOAD
UNLOADED INTO TK 201

Weights	Tank Reading
	<u>2890</u>
	<u>3890</u>

Date 11-22-72 By [Signature]

TUCKER 42

DTH 000004208