

**Region 6 Compliance Assurance and Enforcement Division
INSPECTION REPORT**

Inspection Date(s):	12/18/2017		
Media:	Water		
Regulatory Program(s)	Brine - CWA		
Company Name:	Trinity Operating, LLC		
Facility Name:	Roxy No. 4-20/29H		
Facility Physical Location:	35.0666 N, -96.1697 W		
(city, state, zip code)	Drumright, Oklahoma 74030		
Mailing address:	P.O. Box 1188		
(city, state, zip code)	Houston, Texas 77251		
County/Parish:	Hughes County		
Facility Contact:	Blayne Gunderman		
	713-374-1526		
FRS Number:	N/A		
Identification/Permit Number:	OKU000864		
Media Number:	N/A		
NAICS:	21111		
SIC:	1311		
Personnel participating in inspection:			
Kent W. Sanborn	6EN-WR	Environmental Engineer	(918) 557 – 1615
EPA Lead Inspector Signature/Date			
	Kent W. Sanborn		Date
Supervisor Signature/Date			
	Jerry Saunders		Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Trinity Operating, LLC oil and gas facility located at the latitude 35.0666 N and longitude -96.1697 W near Drumright, Oklahoma on 12/18/2017 for an unannounced inspection. The inspection was conducted by authority of the Clean Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is known as the Roxy No. 4-20/29H site.

Section II - OBSERVATIONS

At the time of the inspection, I observed produced water in the small draw or ditch behind the pad site along the flow path towards the tributary. With a calibrated YSI Pro 30 Conductivity Meter I measured Total Dissolved Solids (TDS) that ranged from 3,000 mg/L to 13,000 mg/L. I did not observe remedial operations during the inspection. I observed erosion on the backside of the pad site causing runoff to the tributary.

Section III – AREAS OF CONCERN

Elevated levels of TDS are present in the tributary.

Section IV – FOLLOW UP

N/A

Section V – LIST OF APPENDICES

N/A