

Leak Detection and Elimination Sheet

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
10-19-01 06:30	5138 TB	GC 1 4	5.1	major leak 9 Sept 5.1 gpm	yes	173497 yes	isolate valve for maint pull line down nothing found	10/19	MAINT	D.H.
10-19-01 07:10	5138 CN	GC 5 8	6.6	Jeffrey Leak NO Same 5137	0	NO	Jeffrey isolate valve for maint	10/19	MAINT	D.H.
10-19-01 07:30	5140 TB	GC 1 3+4	5.3/5.3	RO-ATES 0740	10 yes	173497 yes	pull line down nothing found	10/19	MAINT	D.H.
10-19-01 11:30	5141 CN	GC 3 10	7.0	Jeffrey Not Found	0	NO	pull line down nothing found			
10-19-01 19:10	5142 CH	#1 #3 788	7.4 8.4	Cleared next check	NA	NA	NA	NA	NA	NA
10-19-01 03:55	5143 GS	GC #5 1	19.0	Spot #14 North Rigged in	20	173636 yes	charged north rigged fine	10/24/01	MAINT	D.H.

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.
This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.

Leak Detection and Elimination Sheet

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
10-19-01	GC#5 5144	GC#5 #10	10.0	Found nothing	0	no	Found nothing			
04100	GS			GR			Clear			
10-19-01	5145	#2	7.6	Not Found	NA	NA	NA	NA	NA	NA
0330	CH	#9		Cleared next check						
10-20-01	5146	#1		South Middle	0		Found Nothing			
06100	PS	4	6.7				EM			
10-20-01	5147	GC5	5.5	COMP SHED (EAST)	0		Found Nothing			
0600	CN	4		EM			EM			
10-20-01	5148	GC5	10.0	EM	0		Found Nothing			
0620	CN	3+4	7.4	W. Station (EAST)	0		Found Nothing			
				comp. shed (EAST)	0		Found Nothing			
10-20-01	5149	GC5		EM			Found Nothing			
0625	ID	#5	7.9	EM	no -0-	no	Found nothing			
				P. Williams			Patrick Williams			

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph. ⁴
 This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.