



Applied Environmental Services

"Consultants in Wastes Management and Environmental Control"

ASBESTOS MGMT • AIR POLLUTION STUDIES • HAZARDOUS WASTE/RCRA COMPLIANCE • ENVIRONMENTAL AUDITS

4100 RIO BRAVO

SUITE 320

EL PASO, TEXAS 79902

(915) 533-4108

PLAINTIFF'S EXHIBIT

CHV-809

10 November 1987

Rafael Nickolas, Jr. President
Applied Environmental Services
716 La Cruz
El Paso, Texas 79902

Dear Mr. Nickolas:

The following sample were run for asbestos using method NIOSH 7400A:

Number	Time=minutes	Flow-lpm	Fibers/cc
S-5, Area I, removal	240	15	0.31
S-7, Area III, removal	92	15	0.02

Sincerely,

Howard G. Applegate

Howard G. Applegate
Ph.D.

Chevron BB
015612



Applied Environmental Services
4100 Rio Bravo Suite 320
El Paso, Texas 79902

CLIENT: DARLA ENVIRONMENTAL, SPECIALISTS

PROJECT: CHEVRON

DATE: NOVEMBER 10, 1987

ANALYZED BY: DR. HOWARD APPELGATE

DATE: NOVEMBER 10, 1987

SAMPLE NO.	S-4	S-5	S-6	S-7				
SAMPLE LOCATION	AREA I PERSONAL SAMPLE REMOVAL	AREA I AREA SAMPLE REMOVAL	AREA III PERSONAL SAMPLE REMOVAL	AREA III AREA SAMPLE				
FILTER SIZE (mm)	25	25	25	25				
START TIME	10:00am	10:00am	12:30pm	12:35pm				
END TIME	2:00pm	2:00pm	2:05pm	2:07pm				
RATE OF FLOW (lpm)	2LPM	15LPM	2LPM	15LPM				
TOTAL TIME (hrs)	4HR.	4HR.	3HR.35MIN	1HR.22MIN				
VOLUME SAMPLED (l)	480	3600	190	1230				
RESULTS (f/cc)	0.11	0.31	0.24	0.02				