

PROPOSED REPORT FORM FOR FIELD TEST OF

DECALCOMANIA LEAD WARNING SIGNS

C
O
P
Y

Name of station operator Mr. Paul Johnson
Address of station 6000 West Addison Street
Chicago
Illinois

Date decal mounted August 2, 1948

Decal mounted by George W. Rose

Surface on which mounted (painted, porcelain, other)
(describe) New porcelain pumps

Remarks: 8 pumps with lead warning decalcomanias mounted
on each side (16 decals in all).

First Inspection Date November 22, 1948

Check following conditions as they apply:

Unchanged	<u>x</u>		
Faded	—	(Slightly)	— (Badly)
Torn	—	Scratched	—
Discolored	—		

Second Inspection Date 2-4-49

Check following conditions as they apply:

Unchagned	—		
Faded	—	(Slightly)	— (Badly)
Torn	—	Scratched	<u>x</u>
Discolored			

KE 0009433

Third Inspection

Date 6-8-49

Check following conditions as they apply:

Unchanged

-

Faded

-

(Slightly)

-

(Badly)

Torn

-

Scratched

x

Discolored

-

SEE PICTURES