

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#: F L S 1 1 3 0 0 3 8									
						Year-Month-Day: 2 0 2 4 - 0 4 - 3 0									
						EPA Permit # (or RA):									
						Page 1 Of 2									
Inspector(s): Carol Chen (lead), Carla Foy Start Time: 3:10 pm															
End Time: 3:13 pm															
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC														
	Street Address: 5415 Oil Plant Rd														
	City: Jay County: Santa Rosa State: FL Zip: 32565														
	Nature of Business: oil and gas production														
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702														
	Email:														
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319														
	O/O Mailing Address: 5415 Oil Plant Rd														
City: Jay County: Santa Rosa State: FL Zip: 32565															
Well Data from File	Well Name & #: J. E. Jackson #40-4A API No. 09-113-20100 PA No. 311598														
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: OG_627														
	Latitude (°N): 30.959889 Longitude (°W): -87.200008 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	PBTD: 15778' ☐ Other: surface casing 9 5/8" at 3744'														
	Total Depth (ft): 15828' Inner Casing Size (in): 5 1/2" 15828' Tubing Size (in): 2 7/8" 15510' Packer Depth (ft): 15510'														
	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) 15656' Bottom(ft): 15710' Max. Injection Pressure (psig): 7500 N2 gas 4400psi PW														
Field Measurements and Observations	Latitude (°N): 30.959893 Longitude (°W): -87.20003 Elevation (ft):														
	EPA GPS ID: S75322 Well Status (see table): TA If not Active, Reported Date Last Active:														
	Nature of Injected Fluid(s) if any:														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values):														
	DANGER sign is posted: H2S May Be Present..Authorized Personnel Only..Hazardous Operations...														
	This well is inactive. All the gauges read 0 psi. Tubing gauge: 0 psi														
	A red flag was attached to the well, indicating that repairs are needed. Production gauge: 0 psi														
	A sign on the well provides well identification. Surface gauge: 0 psi														
Flow line gauge:															
See reverse for additional observations, comments and photo log															
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN								Signature:							
Digitally signed by CAROL CHEN Date: 2024.06.20 21:31:51 -04'00'															
Version 2018-04-18															

Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	3	8
	Year-Month-Day:	2	0	2	4	-	0	4	-	3	0
	EPA Permit # (or RA):										
							Page	2	of	2	

Field Measurements and Observations (Cont.)

J. E. Jackson #40-4A State Permit No. OG 627 API No. 0911320100

15656' to 15666' (4SPF) 1/15/1974

15656' to 15666' (4SPF) 10/28/2012

15700' to 15710' (4SPF) 5/01/1974

15700' to 15710' (4SPF) 10/28/2012

Photo Log

Photographer: Carol Chen EPA Camera ID: S75332

Photo ID:	RIMG0157	Time:	3:10 pm	Lat (°N):	30.956422	Long (°W)	-87.184015
-----------	----------	-------	---------	-----------	-----------	-----------	------------

Description: injection well, well identification sign, DANGER sign posted: H₂S May Be Present...

Photo ID:	RIMG0158	Time:	3:11 pm	Lat (°N):	30.959888	Long (°W):	-87.200122
-----------	----------	-------	---------	-----------	-----------	------------	------------

Description: **tubing gauge reads 0 psi**

Photo ID:	RIMG0159	Time:	3:12 pm	Lat (°N):	30.959893	Long (°W)	-87.20003
-----------	----------	-------	---------	-----------	-----------	-----------	-----------

Description: **surface gauge reads 0 psi**

Photo ID:	RIMG0160	Time:	3:12 pm	Lat (°N):	30.95986	Long (°W)	-87.200038
-----------	----------	-------	---------	-----------	----------	-----------	------------

Description: **production gauge reads 0 psi**

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description:

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description:

UIC Inspector

Name: Carol Chen

Signature: CAROL CHEN Digitally signed by CAROL CHEN
Date: 2024.06.20 21:32:19 -04'00'

Name: _____

Signature: _____