

Leak Detection and Elimination Sheet

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
4-13-03	6959	#1	6.4/10/10	ERS Filter pack	100	No	Tighten plus	4-13-03	EC	EC
0750	Ch	#8	10/10							
4-15-03	6960	#1	10/9/10	found NO thing						
1815	Ch	#1, 2, 4								
4-16-03	6961	#1	10/28	Not found Cleared next check	No	No	NA	NA	NA	NA
1940	Ch	#5								
4-17-03	6962	5	10	Top 746 bottom 747						
1815	Bm	9, 10								
4-17-03	6963	#5	5.6/6/8.4	Not found	No	No	NA	NA	NA	NA
1910	Ch	#5, 6	5.1/6/6.9/8.2							
4-21-03	6964	1	10.0	5. mid station old side #3 spot	0	NO	card not offload - W. L. Brown			
1250	Bm	4								

This sheet is to be filled out in the event of one (1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.
This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.