

**NATLSCO**

National Loss Control Service Corporation
Long Grove, Illinois 60049-0075 (312) 540-2488

ENVIRONMENTAL SCIENCES LABORATORY, K-2

LABORATORY ANALYSIS REPORT

REPORT DATE DEC. 21, 1988SAMPLES REC'D DEC. 13, 1988REQUEST NUMBER 97368PAGE NUMBER 1 OF REQUEST.

TO:

DIANA FRIESZ
B. F. GOODRICH
RR 1 BOX 15
HENRY

IL 61537

SAMPLE NUMBER	ANALYSIS REQUESTED	RESULTS	
		PPM	
H261	VINYL CHLORIDE ANALYSIS	0.04	
H262	VINYL CHLORIDE ANALYSIS	0.38	
H263	VINYL CHLORIDE ANALYSIS	0.46	
H264	VINYL CHLORIDE ANALYSIS	0.07	
BLANK-1	BLANK... VINYL CHLORIDE ANALYSIS	NONE DETECTED	
BLANK-2	BLANK... VINYL CHLORIDE ANALYSIS	NONE DETECTED	
		Front	Back
K-1	VINYL CHLORIDE	0.45	0.08
		PPM	
H237	VINYL CHLORIDE ANALYSIS	0.22	
H238	VINYL CHLORIDE ANALYSIS	0.16	
H239	VINYL CHLORIDE ANALYSIS	7.4	
H240	VINYL CHLORIDE ANALYSIS	1.1	
H241	VINYL CHLORIDE ANALYSIS	3.8	
H242	VINYL CHLORIDE ANALYSIS	0.29	

COMMENTS:

REL. #19

C MEANS LESS THAN

METHODS: GAS CHROMATOGRAPHY (ROUTINE)

Respectfully submitted,

Joan A. Wronski, CIH, Manager
Environmental Sciences Laboratory

ACCREDITED BY THE AMERICAN INDUSTRIAL HYGIENE ASSOCIATION

**NATLSCO**

National Loss Control Service Corporation
Long Grove, Illinois 60049-0075 (312) 540-2488

ENVIRONMENTAL SCIENCES LABORATORY, K-2

TO:

DIANA FRIESZ
B. F. GOODRICH
RR 1 BOX 15
HENRY

IL 61537

LABORATORY ANALYSIS REPORT

REPORT DATE DEC. 21, 1988

SAMPLES REC'D DEC. 13, 1988

REQUEST NUMBER 97368

PAGE NUMBER 2 OF REQUEST.

SAMPLE NUMBER	ANALYSIS REQUESTED	RESULTS
		PPM
H243	VINYL CHLORIDE ANALYSIS	0.28
H244	VINYL CHLORIDE ANALYSIS	0.82

COMMENTS:
REL. #19
C TEAMS LESS THAN
METHODS CAS CHROMATOGRAPHY (ROUTINE)
Respectfully Submitted,

Joan A. Wronski

Joan A. Wronski, CIH, Manager
Environmental Sciences Laboratory

ACCREDITED BY THE AMERICAN INDUSTRIAL HYGIENE ASSOCIATION

NC 448-1 20M 8-88

PRINTED IN U.S.A.

NGC 04139