



Continental Technical Services

A Facility of The Continental Insurance Companies

RECEIVED

THE ENVIRONMENTAL HEALTH LABORATORY

of

CONTINENTAL TECHNICAL SERVICES

9742 SKILLMAN • DALLAS, TEXAS 75243 • 214/343-2025

ENGINEERING

LABORATORY REPORT 83-0385

83/04/29

PLAINTIFF'S
EXHIBIT
KRC-236

SOUTHWESTERN REFINING CO. INC.

P. O. BOX 9217

CORPUS CHRISTI TX 78469

Attn: DICK WATSON, TECH. ASS'T

ENVIRONMENTAL CONTROL

PO# 097B

EHL
NO.

FIELD
NO.

SAMPLE
MEDIA

SAMPLE
VOL.

ANALYSIS

RESULTS



Continental Technical Services

A Facility of The Continental Insurance Companies

THE ENVIRONMENTAL HEALTH LABORATORY

of

CONTINENTAL TECHNICAL SERVICES

9742 SKILLMAN • DALLAS, TEXAS 75243 • 214/343-2025

LABORATORY REPORT 83-0385

83/04/29

SOUTHWESTERN REFINING CO. INC.

P. O. BOX 9217

CORPUS CHRISTI TX 78469

Attn: DICK WATSON, TECH. ASS'T

ENVIRONMENTAL CONTROL

EHL
NO.

FIELD
NO.

SAMPLE
MEDIA

SAMPLE
VOL.

ANALYSIS

RESULTS



Continental Technical Services

A Facility of The Continental Insurance Companies

THE ENVIRONMENTAL HEALTH LABORATORY

of

CONTINENTAL TECHNICAL SERVICES

9742 SKILLMAN • DALLAS, TEXAS 75243 • 214/343-2025

LABORATORY REPORT 83-0385

83/04/29

SOUTHWESTERN REFINING CO. INC.

P. O. BOX 9217

CORPUS CHRISTI TX 78469

Attn: DICK WATSON, TECH. ASS'T

ENVIRONMENTAL CONTROL

EHL NO.	FIELD NO.	SAMPLE MEDIA	SAMPLE VOL.	ANALYSIS	RESULTS
D4805		CEF	BLANK	ASBESTOS	None Detected
D4806	132583	CEF	240 L	ASBESTOS	0.16 f/cc
D4807	132983	CEF	98 L	ASBESTOS	0.55 f/cc
D4808	232983	CEF	98 L	ASBESTOS	0.32 f/cc
D4809	332983	CEF	102 L	ASBESTOS	<0.26 f/cc
D4810	14683	CEF	90 L	ASBESTOS	<0.29 f/cc

COMMENTS: * CONFIRMED GC/MS

THANK YOU !

Roger E. Hallstein
ROGER HALLSTEIN, Ph.D.
LABORATORY MANAGER