

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	10/31/2023	Time	10:30
Inspection Due	2016-07-10T00:00:00Z	Operator Representative	Thunder Petroleum, LLC		
Operator Info	Thunder Petroleum, LLC 5100 E. Skelly Dr., Suite 600 Tulsa, OK 74135 Phone: 918-638-7054	Inventory ID	OS5574000		
		API Well No			
		Lease Name			
		Well ID	9-A		
Location	NE 24 25N 09E	Status	Inactive	Well Type	Disposal
Latitude	36.631826	Longitude	-96.285575		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	Thunder Petroleum, LLC		
Inspect No.		Date Last MIT	06/10/2016	Last Test Result	Fail
Casing	5.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 556
FLM Canister Pressure		Actual Pressure	Max Volume 6000		
Lease Status	unknown	Determined?	Max Inj Units Barrels Per Month		
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	At the time of the inspection, well OS5574000 was connected but not injecting, there was no well sign present. At the time of the inspection, the tubing valves were not working and there was no access to observe the fluid level in the tubing. Inspector was able to access the annulus of the well and observed no pressure or vacuum present through an open valve. Inspector shot the annular fluid level with the EPA Echometer but the return was immediate indicating the liquid level was very near the land surface, less than 30 feet down hole.				
Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2023.11.29 17:08:16 -06'00'				
Supervisor Signature	JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2023.11.30 08:07:42 -06'00'				

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.631826, -96.285575		
City: Pawhuska	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010224

Orientation: E

Date of Photo: 10/31/2023

Time of Photo: 10:34 AM

Latitude: 36.631826

Longitude: -96.285575

Photographer: Matthew Allen

Description: This was well OS5574000 at the time if the inspection.