

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	04/28/2025	Time	08:45
		Operator Representative	CapturePoint, LLC		
Operator Info	CapturePoint, LLC 1101 Central Expwy S., Suite 150 Allen, TX 75013 Phone: 832-300-8221	Inventory ID	OS0508000		
		API Well No			
		Lease Name	North Burbank Unit		
		Well ID	82-W6		
Location	SW 35 27N 05E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.774004	Longitude	-96.737961		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	CapturePoint, LLC		
Inspect No.		Date Last MIT		Last Test Result	
Casing	5.5	Tubing	2.375	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 801
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Hurricane Services tag the top of the bottom plug at 2155 feet below the surface. Hurricane Services loaded the well with 10 lb/gal mud and perforated the well at 1600 feet below the surface. Hurricane Services spotted 60 sacks of class A cement beginning at 1650 feet below the surface. This was the second or middle cement plug installed into well OS0508000 in accordance with the EPA approved plugging plan.				
Inspector Signature					
Supervisor Signature					