

DATE:

LAM006279

S. W. Graves  
C. M. Hancock  
B. E. Kullers

S. Moncla  
B. Wooley

TEXAS CITY  
INSPECTION RECORD  
TRANSFORMERS AND CAPACITORS IN SERVICE  
(PCB and non-PCB)

FORM A

Page 1 of 2

Inspection Date \_\_\_\_\_  
No \_\_\_\_\_

| Item No.<br>on Dwg. | Equip<br>No. | Descriptive Location                              | Type<br>Fluid | Properly<br>Marked | Evidence<br>of Leaks | Comments                          |
|---------------------|--------------|---------------------------------------------------|---------------|--------------------|----------------------|-----------------------------------|
| 2                   | TS 412-8     | South of 29T503                                   | PCB(1)        |                    |                      |                                   |
| 3                   | TS 412-4     | SE of 16T19-5 (pole mounted)                      | PCB           |                    |                      |                                   |
| 6                   | TS 66-7      | SW of 954T35                                      | Mixed(2)      |                    |                      |                                   |
| CED                 |              |                                                   |               |                    |                      |                                   |
| 8                   | Mobile Sta.  | Varies - Stored on NO. 68                         |               |                    |                      | Retrofilled 1980                  |
| 9                   | TS 16        | West of Salt Water Pump House                     | PCB           |                    |                      | with silicone                     |
| 10                  | TS 7         | SE Corner of 4th Ave. &<br>North St. intersection | PCB           |                    |                      |                                   |
| 11                  | TS 16B       | NW Corner 4th Ave. & Center St.                   | Mixed(3)      |                    |                      |                                   |
| 12                  | TS 8B        | SE Corner 4th Ave. & Center St.                   | Mixed(3)      |                    |                      |                                   |
| 13                  | TS 8A        | NE Corner 4th Ave. & Main St.                     | PCB           |                    |                      |                                   |
| 16                  | TS 16C       | North of Dehydrogenation                          | PCB           |                    |                      |                                   |
| 17                  | TS 66-1      | West of Zone 1 Office Bldg.                       | Mixed(2)      |                    |                      |                                   |
| 19                  | TS 10        | East side North End Dept. 10 Comp. Bldg           | PCB           |                    |                      |                                   |
| 21                  | PCB Stg.     | 1&E Warehouse                                     |               |                    |                      |                                   |
| 23                  | TS 508A      | South of ARMS Bldg.                               | PCB           |                    |                      |                                   |
| 23                  | TS 508       | South of Research No. 1                           | PCB           |                    |                      | Retrofilled 1980<br>with silicone |
| 25                  | TS 140D      | Entrance to East Side of Shop Bldg.               | PCB           |                    |                      |                                   |
| 27                  | TS 66-4      | South of Fire House (across street)               | PCB(4)        |                    |                      |                                   |
| 29                  | TS 412-5     | East of 53T702 (across street)                    | PCB(1)        |                    |                      | retrofilled 1980<br>with silicone |
| 31                  | TS 954       | South of CT-2 (3 transformers)                    | PCB           |                    |                      |                                   |
| 32                  | TS 17        | South of AN Shops Bldg. (2 transformers)          | PCB(4)        |                    |                      | 1 retrofilled                     |
| 36                  | TS 51        | South of AN Control House (2)                     | PCB           |                    |                      |                                   |
| 37                  | TS 44        | South of Methanol Control House                   | PCB           |                    |                      |                                   |

- 1) Oil contaminated with PCB
- 2) Transformers non-PCBm, capacitors PCB
- 3) Transformers PCB, transformers PCB contaminated oil
- 4) Capacitors PCB, transformers PCB contaminated oil
- 5) Capacitors non-PCB, transformers PCB contaminated oil

INSPECTED BY: \_\_\_\_\_

## FORM A

TEXAS CITY  
INSPECTION REPORT  
TRANSFORMERS AND CAPACITORS IN SERVICE  
(PCB and non-PCB)

Page 2 of 2

Inspection Date \_\_\_\_\_

| Item No.<br>on Dwg. | Equip<br>No. | Descriptive Location                               | Type<br>Fluid | Properly<br>Marked | No<br>Evidence<br>of Leaks | Comments             |
|---------------------|--------------|----------------------------------------------------|---------------|--------------------|----------------------------|----------------------|
| 39                  | TS 66-2      | SW of Warehouse D                                  | Mixed(2)      |                    |                            |                      |
| 40                  | TS 60        | NE Corner 4th Ave. West and South<br>Center Street | PCB           |                    |                            |                      |
| 41                  | TS 66-6      | SW Corner 4th Ave. West & South St.                | Mixed(5)      |                    |                            |                      |
| 42                  | TS 50        | North of Acetic Acid Control House                 | PCB           |                    |                            |                      |
| 43                  | TS 33        | NW of CT-8                                         | PCB           |                    |                            |                      |
| 44                  | CED          | East of Opel Shops Bldg.                           | PCB(1)        |                    |                            |                      |
| 46                  | TS 48        | North of Oxo-Esters Control House (2)              | PCB           |                    |                            |                      |
| 47                  | TS 53        | East of Dept. 53 Control House<br>(2 transformers) | PCB           |                    |                            | Retrofilled silicone |
| 49                  | TS 66-5      | East of Pellet Trap                                | Mixed(2)      |                    |                            |                      |
| 53                  | TS 35AN      | NE Corner Dept. 35 Control House (2)               | PCB           |                    |                            |                      |
| 55                  | TS 35BN      | West of Dept. 35 Control House                     | PCB           |                    |                            |                      |
| 56                  | TS 140C      | East of West Gate House                            | Silicone/PCB  |                    |                            | Retrofilled 1981     |
| 58                  | TS 66-3      | West of 710T4 (SW corner of plant)                 | Mixed(5)      |                    |                            |                      |

- 1) Oil contaminated with PCB
- 2) Transformers non-PCB, capacitors PCB
- 3) Transformers PCB, transformers PCB contaminated oil
- 4) Capacitors PCB, transformers PCB contaminated oil
- 5) Capacitors non-PCB, transformers PCB contaminated oil

INSPECTED BY: \_\_\_\_\_