



INSPECTION REPORT

Facility Inspected Salvation Army
16 Felton Place
Cartersville, Georgia 30120

Inspection Date: May 18, 2022

Facility Programmatic ID 3601430857
LAT: 34.1950 LON: -84.7933

Inspection Type Clean Air Act (CAA)
National Emission Standards for Hazardous Air Pollutants (NESHAP) - Asbestos

Inspectors Tony Spann (Lead)
Pamela Storm

Introduction

An inspection pursuant to Section 114 of the CAA was conducted on May 18, 2022, at the Salvation Army located at 16 Felton Place in Cartersville, Georgia 30120 (the facility). The unannounced inspection was conducted by Tony Spann and Pamela Storm of EPA Region 4.

Old South Excavating obtained demolition permit # 21110007 for the demolition activity at the facility from Bartow County on November 1, 2021. The inspectors obtained information regarding this permit from Bartow County on May 18, 2022, prior to this inspection. The purpose of the inspection was to determine compliance with the CAA NESHAP Asbestos Standard and the regulations promulgated at 40 C.F.R. Part 61, Subpart M, for the demolition activity conducted pursuant to this permit.

The EPA Region 4 CAA NESHAP asbestos program targets facilities for inspection located in the State of Georgia based on tips/complaints; permits issued on a local level; and demolition and/or renovation/abatement notices sent to the State. This inspection was conducted based on the previously mentioned permit.

Facility Information

The facility is a Salvation Army store in which the demolition activity was performed.

Inspection

Ms. Barbara Gidders, the representative of the facility at the time of this inspection, explained to the inspectors that she was unaware of what demolition activities were performed at the facility. She provided the contact information for Major Michelle Pearson and Major Grady Pearson, the owners of the facility.

The demolition activity at the facility had been completed at the time of this inspection. No evidence of ongoing renovation or demolition activities were observed by the inspectors.

Conclusion

The inspectors will follow up with Old South Excavating, the contractor listed on the demolition permit, and/or owners/operators, as deemed appropriate, to obtain information and necessary paperwork related to this demolition activity. This information will include, but not necessarily be limited to, copies of asbestos inspection reports and demolition notifications for the facility.

Report Approval

This inspection report was written by:

Spann, Tony
Digitally signed by Spann, Tony
Date: 2022.07.18 15:44:35 -04'00'

Tony Spann, Inspector-In-Training

This inspection report was reviewed by:

PAMELA STORM
Digitally signed by PAMELA STORM
Date: 2022.07.21 15:03:14 -04'00'

Pamela Storm, Inspector

This inspection report was approved by:

JASON DRESSLER
Digitally signed by JASON DRESSLER
Date: 2022.07.22 10:51:09 -04'00'

Jason Dressler, Chief
North Air Enforcement Section