

PLAINTIFF'S EXHIBIT

MON-2417

TC Asbestos Monitoring

Standard effective July 1, 1976:

15' ceiling = 10 Fb/cc

8-hr TWA = 2 "

Date	Sample Type	Determination Type	Results	Remarks
5-5-76	Area	Engineering	0.00	Dismantling (41 & 42
	"	"	0.05	" A/C Rm
	"	"	0.00	"
	"	"	0.00	Sampling A/C 42 D
	"	"	0.00	Offthr. Sample 41 D
	"	"	0.00	"
	"	Other	0.00	Training Rm - 41 D
	"	"	0.00	Gen. Rm. Area 42 D
	"	"	0.03	Near 42 N1-5
6-9-76	Personnel	TWA	0.04	16075th Line - ^{non asb.} insulati.
	"	"	0.00	SOD Insulating
	Area	Job/Task	0.00	20' DW Crane Moving Ec
	"	"	0.02	50' DW " " "
6-10-76	Personnel	TWA	0.05	Res II - Stripping lines
	"	"	0.06	SOD - Install FG & strip ka
	"	"	0.01	SOD - Install Foam Glass
	"	"	0.01	Res II - Insulating lines
6-17-76	Personnel	Job/Task	0.71	Res II - Pipe Insul Tear Out
	"	"	1.04	" " " " "
8-4-76	Personnel	Ceiling	0.40	19D, #3 R ₁ , Insul. Tear Out
	"	"	0.28	" " " " "
1-31-77	Personnel	Job/Task	11.40	Res II, Lab 2113, Removing Insul. B
	"	"	8.89	" " " " "
2-4-77	Source	Job/Task	5.19	Res II, Drilling asb. board
4-17-78	Gen. Area	Job/Task	0.68	Contractors Remove Insul - 0
	"	"	0.00	" " " "
5-17-78	Personnel	Ceiling	0.21	P2 - Stripping 20" stm line
	"	"	0.00	" " " "
	Gen. Area	"	0.00	" " " "
	"	"	0.00	" " " "
	Personnel	"	0.00	" " " "

6113
19060

LAM021818

Date	Sample Type	Determination Type	Results	Remarks
5-17-78	Gen. Area	Ceiling	0.00	P2 Stripping 20" stm Line
	"	"	0.00	" " "
5-23-78	Gen. Area	Ceiling	0.00	P2 Contractors Removing Insul.
	"	"	0.00	" " "
	"	"	0.00	" " "
2-9-79	Source Personnel	Ceiling	0.00	2' from man, Grinding Bondstrand, f
		"	0.00	Grinding Bondstrand pipe - P2
2-14-79	Source	Engineering	5.51	PT Alc Rm; Contractors Strip pipe, ^{full} prot
	Gen. Area	"	3.27	" " " "
	"	"	0.44	" " " "
	Source	"	6.61	" " " "

6113
19061

LAM021819