FILE NAME: International Harvester (INTH)

DATE: 1978 June

DOC#: INTH021

DOCUMENT DESCRIPTION: Memo - Notes on Sampling

June 78 –

Sludge from Henry tanks

Balance tank - McGill - or Dorr Oliver

Cupola refractory -

Type R · Rotoclone for shakers

Dust on overhead steel SM · 1 area

(Asbestos - in raw water - feedwater)

★ Call Lisa Yeo - for results (if available)

Alexandria - 703 - 557 - 5040

Sample # A · 0272 EMS Labs in

Hawthorne Cal - LVW0292

March 20 - Leslie foundry -

Bottle #1 Sludge from Henry tank -

initial settling tank -

" #2 - Water from above tank -

" #3 - Surface material plus H_2O on above tank

" #4 - Filter cake from Dorr-Oliver

Cupola off take -

" #5 Sample of Meltzona mined material

(Blast patch is another name mixed with H_2O - sprayed on cupola

lining for repair.

bottle # 6 Premix (contains bentonite) Mined in different area - not Western

" # 7 Western ~~Sea coal~~ Bentonite

" # 8 - Sea coal

" # 9 - Slag - from slag trough at tap hole - # 4 cupola.

" # 10 - Water - city -

" # 11 - Cope seal - 2 boxes/week (tab + asbestos? rope)

LVW0293