

TEXAS DEPARTMENT OF HEALTH DEMOLITION / RENOVATION NOTIFICATION FORM

NOTE: CIRCLE ITEMS THAT ARE AMENDED.



NOTIFICATION#

- 1) Abatement Contractor: Darla Southwest Inc. TDH License Number: 80-0055
 Address: 6138 Yaqui Way City: El Paso State: TX Zip: 79925
 Office Phone Number: (915) 772-8181 Job Site Phone Number: () N/A
 Site Supervisor: _____ TDH License Number: 80-3154
 Site Supervisor: _____ TDH License Number: 80-3789
 Trained On-Site NESHAP Individual: N/A Certification Date: N/A
- Demolition Contractor: N/A Office Phone Number: () N/A
 Address: N/A City: N/A State: N/A Zip: N/A
- 2) Project Consultant or Operator: Sun City Analytical, Inc. TDH License Number: 10-0011
 Mailing Address: 1409 Montana Avenue
 City: El Paso State: TX Zip: 79902 Office Phone Number: (915) 533-8840
- 3) Facility Owner: Asarco Incorporate
 Attention: Peggy Munsell
 Mailing Address: P.O. Box 1111
 City: El Paso State: TX Zip: 79999 Owner Phone Number: (915) 521-3640
- 4) Description or Facility Name: Power House Bldg\Reverb
 Physical Address: 2301 W. Paisano County: El Paso
 City: El Paso Zip: 79922 Facility Phone Number: (915) 541-1800
 Facility Contact Person: Peggy Munsell
 Description of Area/Room Number: Throughout Bldg
 Prior Use: Power House\Reverb Future Use: Power House\Reverb
 Age of Building/Facility: 77 Yrs Size: 18,000 s.f. Number of Floors: 2 Story
 School (K-12): ☐ YES ☒ NO
- 5) Type of Work: ☐ Demolition ☒ Renovation (Abatement) ☐ Annual Consolidated
 Work will be during: ☒ Day ☐ Evening ☐ Night ☐ Phased Project
 Description of work schedule: Monday-Friday 8:00 to 5:00 p.m.
- 6) Is this a Public Building? ☐ YES ☒ NO Federal Facility? ☐ YES ☒ NO Industrial Site? ☒ YES ☐ NO
 NESHAP-Only Facility? ☒ YES ☐ NO Is Building/Facility Occupied? ☐ YES ☒ NO
- 7) Notification Type CHECK ONLY ONE
☒ Original (10 Working Days) ☐ Cancellation ☐ Amendment ☐ Emergency/Ordered
 If this is an amendment, which amendment number is this? N/A (Enclose copy of original)
 If an emergency, who did you talk with at TDH? N/A Emergency# N/A
 Date and Hour of Emergency (HH/MM/DD/YY): N/A
 Description of the sudden, unexpected event and explanation of how the event caused unsafe conditions or would cause equipment damage (computers, machinery, etc.): N/A
- 8) Description of procedures to be followed in the event that unexpected asbestos is found or previously non-friable asbestos material becomes crumbled, pulverized, or reduced to powder: Affected area will be immediately restricted with barrier tapes and poly. ACM will be cleaned up by Hepa Vacs and wet wiped. Air monitoring will be indicated. Local authorities to be contacted.
- 9) Was an Asbestos survey performed? ☒ YES ☐ NO Date: 04/28/99 TDH Inspector License No: 60-1889
 Analytical method: ☒ PLM ☐ TEM ☐ Assumed TDH Laboratory License No: 30-0011
 (For TAPPA (public building) projects: an assumption must be made by a TDH Licensed Inspector)
- 10) Description of planned demolition or renovation work, type of material, and method(s) to be used: Abate ACM pipe insulation & pipe insulation using appropriate Methods & procedure replace with NON-ACM.
- 11) Description of work practices and engineering controls to be used to prevent emissions of asbestos at the

demolition/renovation site: Area restricted, full containment with negative pressure, wet removal methods, HEPA vacuum clean up, air monitoring

- 12) ALL applicable items in the following table must be completed: IF NO ASBESTOS PRESENT CHECK HERE ☐

Asbestos-Containing Building Material Type	Approximate amount of Asbestos		Check unit of measurement					
	Pipes	Surface Area	Lt Ft	Lt M	SQ Ft	SQ M	Cu Ft	M
RACM to be removed	3,500	800	XX		XX			
RACM NOT removed								
Interior Category I non-friable removed								
Exterior Category I non-friable removed								
Category I non-friable NOT removed								
Interior Category II non-friable removed								
Exterior Category II non-friable removed								
Category II non-friable NOT removed								
RACM Off-Facility Component								

- 3) Waste Transporter Name: DARLA Southwest, INC. TDH License Number: 40-0127
 Address: 6138 Yaqui Way City: El Paso State: TX Zip: 79925
 Contact Person: Jay Block Phone Number: (915) 772-8181
- 4) Waste Disposal Site Name: Otero Lincoln County Landfill
 Address: 23 Miles South on Hwy 54 City: Alamogordo State: NM Zip: 88310
 Telephone: (505) 439-4355 TNRCC Permit Number: SWN 190103
- 5) For structurally unsound facilities, attach a copy of demolition order and identify Governmental Official below:
 Name: N/A Registration No: N/A
 Title: N/A
 Date of order (MM/DD/YY) N/A Date order to begin (MM/DD/YY) N/A
- i) Scheduled Dates of Asbestos Abatement (MM/DD/YY) Start: 06/01/99 Complete: 06/25/99
- j) Scheduled Dates Demolition/Renovation (MM/DD/YY) Start: N/A Complete: N/A

Note: If the start date on this notification can not be met, the TDH Regional or Local Program office *Must* be contacted by phone prior to the start date. Failure to do so is a violation in accordance to TAPPA, Section 295.61. **

I hereby certify that all information I have provided is correct, complete, and true to the best of my knowledge. I acknowledge that I am responsible for all aspects of the notification form, including, but not limiting, content and submission dates. The maximum penalty is \$10,000 per day per violation.

Peggy Munsell Peggy Munsell 05/13/99 (915) 521-3640
 Signature of Building Owner/ Operator (Printed Name) (Date) (Telephone)
 Delegated Consultant/Contractor (915) 541-1811
 (Fax Number)

IL TO:

ASBESTOS NOTIFICATION SECTION
 TOXIC SUBSTANCES CONTROL DIVISION
 TEXAS DEPARTMENT OF HEALTH
 EXCHANGE BUILDING, SUITE N320
 8407 WALL STREET
 AUSTIN, TX 78754


es are not accepted*

PH: 512-834-6600, 1-800-672-5548

Faxes are not accepted

n APB#5, dated 12/08/98. Replaces TDH form dated 09/15/97. For assistance in completing form, call 1-800-572-5548

ASARCO ELP 0013123



Sun City Analytical Inc.

ENVIRONMENTAL SERVICES

1409 Montana
El Paso, Texas 79902
(915) 533-8840
Fax (915) 533-88430
E-Mail = ***SCAI@Flash.net***



ASARCO ELP 0013124