

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	3/4/2025	
Media Program:	Water	
Regulatory Program(s)	Clean Water Act	
Company Name:	Lamkin Oil, Inc.	
Facility Name:	Linkous B Tank Battery	
Facility Physical Location:	Latitude: 33.422286 Longitude: -93.037606	
(city, state, zip code)	Stephens, AR, 71764	
Mailing address:	215 Highway 332	
(city, state, zip code)	Stephens, AR 71764	
County/Parish:	Ouachita County	
Facility Phone Number	870-786-5306	
Facility Contact:	Travis Lamkin clamkin@gmail.com	
FRS Number:	NA	
Identification/Permit Number:	ARU002298	
Media Identifier Number:	NA	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Michael Blaha (lead)	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Kerri McCabe	EPA/Region 6 ECDW	Enforcement Officer/Inspector
EPA Lead Inspector Signature/Date		
	Michael Blaha	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Michael Blaha and Kerri McCabe arrived at Lamkin Oil, Inc. – Linkous B Tank Battery, located off Ouachita Road 8 (33.422286, -93.037606) at 1:10 PM on March 4, 2025, for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection on the Lamkin Oil, Inc. – Linkous B Tank Battery, which consists of one (1) separator, and four (4) storage tanks.

Section II - OBSERVATIONS

I observed the facility sign, secondary containment, pipes, valves, and storage tanks located at the facility; see Appendix 1 (photo log), photo No. 1 and No. 2. For additional GPS location and photo metadata, see Appendix 1.

I observed loose oil and sheen inside secondary containment, see photo No. 3.

I observed gapping under the storage tanks, see photo No. 4.

Section III – AREAS OF CONCERN

No closing conference was held due to no Lamkin Oil, Inc. staff being present during the inspection. Areas of concern at the time of the inspection include loose oil inside secondary containment and gapping under the tanks.

Section IV – FOLLOW UP

Inspector will conduct follow-up phone calls with the company representatives over the coming weeks and months to ensure areas of concern are properly addressed.

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – 4 photos taken on 3/4/2025

Appendix 1

Photograph Log

4 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 33.422286, -93.037606		
City: Stephens	County/Parish: Ouachita	State: Arkansas



Photo File Name: 20250304_191117752_iOS

Orientation: NW

Date of Photo: 3/4/2025

Time of Photo: 1:11 PM

Latitude: 33.422286

Longitude: -93.037606

Photographer: Michael Blaha

Description: This photo was taken looking northwest and shows the facility sign.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 33.422286, -93.037606		
City: Stephens	County/Parish: Ouachita	State: Arkansas



Photo File Name: 20250304_191242573_iOS

Orientation: N

Date of Photo: 3/4/2025

Time of Photo: 1:12 PM

Latitude: 33.422128

Longitude: -93.037566

Photographer: Michael Blaha

Description: This photo was taken looking north and shows an overview of the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: 33.422286, -93.037606		
City: Stephens	County/Parish: Ouachita	State: Arkansas



Photo File Name: 20250304_191354772_iOS

Orientation: W

Date of Photo: 3/4/2025

Time of Photo: 1:13 PM

Latitude: 33.42225

Longitude: -93.03765

Photographer: Michael Blaha

Description: This photo was taken looking west and shows loose oil and sheen inside secondary containment.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Location: 33.422286, -93.037606		
City: Stephens	County/Parish: Ouachita	State: Arkansas



Photo File Name: 20250304_191554885_iOS

Orientation: NE

Date of Photo: 3/4/2025

Time of Photo: 1:15 PM

Latitude: 33.422355

Longitude: -93.037797

Photographer: Michael Blaha

Description: This photo was taken looking northeast and shows gapping under the tanks.