

BASIC INFORMATION

FACILITY INFORMATION

OPENING CONFERENCE

No opening conference was conducted because no site representatives were present at the time of the inspection. The facility gate was closed at the time of the inspection, so the evaporation pond and other equipment were viewed from outside the gate. We did not enter the facility during the inspection.

Facility Name: McGinnis OWDF
Facility Location: 42.364319, -110.324708
Date of Inspection: May 16, 2023

TOUR INFORMATION

Areas of the Facility viewed:

- evaporation pond,
- tank battery, and
- tanker offload area.

Data Collected and Observations: During the inspection I observed that bird balls covered most of the surface area of the evaporation pond. No RCRA concerns were noted at the site. No photographs were collected during this inspection.

CLOSING CONFERENCE

No closing conference was conducted because no site representatives were present.

SIGNATURE & DATE

Lead Inspector: _____
Annette Maxwell, RCRA Inspector

Supervisor: _____
Janice A. Pearson, Manager
RCRA & OPA Enforcement Branch
Enforcement and Compliance Assurance Division