

cc: Rossi
Harris
Clark

EUL 22 1970



George Marr, Safety Engineer I

Newark

Otto Young, Safety Engineer Assistant

4646-CA

ckg

Owens-Corning Fiberglas Corporation
Jackson Road
Berlin, New Jersey

July 15, 1970

Please be advised that a visit was made to the subject location on June 10, 1970, accompanied by the following:

Mr. George Marr, Safety Engineer I
Anthony J. Rossi, Chief, Safety Inspection Section
J. Taylor, Industrial Hygienist, Department of Health

A visual inspection was made of the following locations:

1. Mold cleaning area where steel molds are sand blasted clean.
2. Iron chromite and asbestos storage area.
3. Batch mixing area - asbestos, clay.
4. Product control laboratory.
5. Autoclave area - drying - 17 auto claves.
6. Pouring and mold release area (dust).
7. Molded Pipe trim saw area (dust).
8. Packing area (dust).
9. New molded pipe trim saw area.
10. Packing area.
11. Dowtherm storage, heating and filtering area.

Made vapotester sampling of Dowtherm vapors in Dowtherm heating and storage area. No results. Company uses approximately 2000 gallons of Dowtherm per year.

Results of survey pending results of dust samples collected by Department of Health.

ENGINEERING SECTION

To:
Prepare Letter Issue Order
Initial & Pass Field Insp.
Submit Report Schedule
Give Comments See Me
Other:
Date Chief Safety Engr.

Otto Young

[Handwritten signature]
9/17/70