

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	K	Y	S	1	5	3	0	1	4	1
Year-Month-Day:					2	0	2	4	-	1	0	-	2	2	
EPA Permit # (or RA):					R	A									
					Page	1		Of	2						
Inspector(s): Carol Chen (lead), Lonnie Dorn Start Time: 9:30 am															
End Time: 9:31 am															
Facility Contact Information	Facility Name: Slone Energy, LLC														
	Street Address: 8966 KY RT 40 West, P.O. Box 220														
	City: Oil Springs County: Magoffin State: KY Zip: 41238														
	Nature of Business: oil production														
	Facility Owner/Operator: Mr. S. Chris Slone, PE Phone: 606.297.5330 work														
	Email: chrisslone@sloneenergy.com														
	Facility Contact (if different): Phone: 606.225.2206 cell														
	O/O Mailing Address:														
	City: County: State: Zip:														
Well Data from File	Well Name & #: SALYERS HEIRS #W-3														
	Well Type (see table): Class II-R, Enhanced Oil Recovery (EOR) State Permit:														
	Latitude (°N): 37.70743 Longitude (°W): -83.01495 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	☐ Other: 4 1/2" production casing														
	Total Depth (ft): Inner Casing Size (in): 2 3/8" Tubing Size (in): 1" Packer Depth (ft):														
Field Measurements and Observations	Inj. Zone: ☐ Open Hole; ☐ Perforated; Top(ft) Bottom(ft): Max. Injection Pressure (psig):														
	Latitude (°N): 000 Longitude (°W): 000 Elevation (ft):														
	EPA GPS ID: S75332 Well Status (see table): TA If not Active, Reported Date Last Active: 7/07/2010														
	Nature of Injected Fluid(s) if any:														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values):														
	The injection line is disconnected and the wellcap shows corrosion.														
See reverse for additional observations, comments and photo log															
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN								Signature:							
Digitally signed by CAROL CHEN Date: 2024.12.11 13:51:02 -05'00'								Version 2018-04-18							

Inspection ID	EPA Well ID#:	K	Y	S	1	5	3	0	1	4	1
	Year-Month-Day:	2	0	2	4	-	1	0	-	2	2
	EPA Permit # (or RA):	R	A								
					Page	2		Of	2		

(Cont)

SALYERS HEIRS #W-3

Photographer: Carol Chen EPA Camera ID: S75332

Photo ID: RIMG0179 Time: 9:31 am Lat (°N): 000 Long (°W): 000

Description: view of the injection well

Photo ID: RIMG0180 Time: 9:31 am Lat (°N): 000 Long (°W): 000

Description: farther back, view of the injection well

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

UIC Inspector

Name: _____

Signature: _____