

UNION CARBIDE CHEMICALS AND PLASTICS COMPANY INC.
POLYOLEFINS DIVISION

May 27, 1993

RECEIVED
JUN 02 1993

Texas Air Control Board
12124 Park 35 Circle
Austin, Texas 78753

Basic Industries
9139 Wallisville
Houston, Texas 77029

Attn: Asbestos Notification Section

CERTIFIED MAIL/RETURN RECEIPT REQUESTED

Re: Removal of Insulation Containing Asbestos

Per requirements of 40 CFR 61 the attached notification is for the renovation of facilities containing friable insulation.

During June 14 through June 28 we plan to remove an estimated 600 linear feet of insulation containing asbestos located in our Oxide Derivatives Unit. The contractor doing the asbestos is Basic Industries.

Please contact me at (512) 553-3091 if there are questions concerning information contained in this notification.

Sincerely,

S. G. Bone

SGBdlg

Attachment

CC: Mr. J. R. Battalora -306
Mr. F. A. Berger - 164
Mr. J. Davis, Basic Industries
EP File 202.07.01.02
05SG85/93

015357



NOTIFICATION OF DEMOLITION AND RENOVATION

Operator Project #	Postmark	Date Received	TDH Notified?	Notification #
I. TYPE OF NOTIFICATION (O=Original R=Revised C=Cancelled): 0				
II. FACILITY INFORMATION (Identify owner, removal contractor, and other operator)				
OWNER NAME: Union Carbide Chemicals and Plastics Company				
Address: P. O. Box 186				
City: Port Lavaca	State: Texas	Zip: 77979		
Contact: Steven Bone			Tel: (512) 553-3091	
REMOVAL CONTRACTOR: Basic Industries				
Address: 9139 Wallisville		TDH Lic. No: 80-0155		
City: Houston	State: Texas	Zip: 77029		
Contact: Johnny Davis			Tel: (713) 671-9036	
OTHER OPERATOR:				
Address:				
City:	State:	Zip:		
Contact:			Tel:	
III. TYPE OF OPERATION (D=Demo O=Ordered Demo R=Renovation E=EmerRenovation P=Planned): R				
IV. IS ASBESTOS PRESENT? (Yes/No): Yes				
V. FACILITY DESCRIPTION (Include building name, number and floor or room #)				
Unit Name: Plant Facilities		TACB Account:		
Address: Highway 185		County: Calhoun		
City: Port Lavaca	State: Texas	Zip: 77983		
Site Location: Oxide Derivatives Unit			Site Tel: (512)553-3091	
Building Size:	# of Floors:	Age in Years: 35		
Present Use: Chemical Manufacturing		Prior Use: Chemical Manufacturing		
VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Visual inspection and bulk sample analysis				
015358				
VII. APPROXIMATE AMOUNT OF ASBESTOS, INCLUDING:		Nonfriable Asbestos Material Not To Be Removed		Indicate Unit of Measurement Below
1. Regulated ACM to be Removed	RACM To Be Removed	Cat I	Cat II	UNIT
2. Category I ACM Not Removed				
3. Category II ACM Not Removed				
Pipes	600			LnFt: X Ln m:
Surface Area				SqFt: Sq m:
Vol RACM Off Facility Component				CuFt: Cu m:
VIII. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 06-14-93 Complete: 6-28-93				
IX. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 06-14-93 Complete: 6-28-93				

Please Type or Print

ACB-99B (3/1/91)

NOTIFICATION OF DEMOLITION AND RENOVATION (continued)

X. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:		
Strip RACM Insulation from Process Piping		
XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION AND RENOVATION SITE:		
Glove bag and wet removal with Engineering controls		
XII. WASTE TRANSPORTER #1		
Name: Brown & Root Industrial Services		
Address: P. O. Box 186		
City: Port Lavaca	State: Texas	Zip: 77979
Contact: M. G. Gonzales		Tel: (512) 553-2473
WASTE TRANSPORTER #2		
Name:		
Address:		
City:	State:	Zip:
Contact:		Tel:
XIII. WASTE DISPOSAL SITE		
Name: On-Site Landfill		
Address:		
City:	State:	Zip:
Telephone:	TDH/TWC Permit No.: HW-50190	
XIV. IF DEMOLITION ORDERED BY GOVERNMENT AGENCY, PLEASE IDENTIFY AGENCY BELOW:		
Name:	Title:	
Authority:		
Date of Order (MM/DD/YY):	Date Ordered to Begin (MM/DD/YY):	
XV. FOR EMERGENCY RENOVATIONS		
Date and Hour of Emergency (HH/MM/DD/YY):		
Description of the Sudden, Unexpected Event:		
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:		
XVI. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER.		
015359		
XVII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS. (Required 1 year after promulgation)		
Job Supervisor: Juan Martinez		5/27/93
TDH Lic. No.: 80-2298	(Signature of Owner/Operator)	(Date)
XVIII. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT.		
		5/27/93
(Signature of Owner/Operator)		(Date)

Please Type or Print

ACB-99C (3/1/91)