

Leak Detection and Elimination Sheet

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
1-7-00 3242	AS	#4	8.3	TOP OF RX 744	None	—	None			
1-7-00 3243	BN	Tank Farm GC #1	5.6	10M Railcar unloading Compress, shed	6	NO	nothing Repair	1-7	JP	JP
1-7-00 3244	BN	Tank Farm GC #1	10.4-5.2 6.5 10.4 6.0 9.4	10M Railcar unloading Compress, shed 10M Railcar unloading Reaction	5	NO	pulled pot at Back of #1 comp. down	1-7	TC	TC
1-7-00 3245	AS	1	5.7	SOUTH STATION NEW EAST UNLOADING	0	NO	found nothing	1-7	BC	BC
1-7-00 3246	AS	1	7.7 10.0 10.0	SOUTH STATION NEW EAST UNLOADING	0	NO	found Nothing	1-7	TC	TC
1-7-00 3247	AS	2	6.1	TOP OF 742 REACTOR	0	NO	Nothing Found	1-7	TM	TM

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.

This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.