

Inspection Report Addendum for Well: MT20766-04254
Inspection Date: 10/24/2023

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20766-04254 (101-W7), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 1 of 2	Time: 4:54 pm		
Photo Description: Operator noted that well has been plugged and abandoned. Inspector visited location of well to confirm that wellhead does not exist.			

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20766-04254 (101-W7), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 2 of 2	Time: 4:54 pm		
Photo Description: Operator marked the location the well had previously been located during the inspection.			

 Inspector signature

 Inspector signature

 Inspector signature