

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	08/04/2022	Time	12:10
Inspection Due	2020-04-08T00:00:00Z	Operator Representative	Raptor Resources, LLC		
Operator Info	Raptor Resources, LLC 63555 North Indigo Trail Owasso, OK 74055 Phone: 918-440-3585	Inventory ID	OS6222000		
		API Well No			
		Lease Name	Blackland		
		Well ID	10		
Location	NW 01 27N 07E	Status	Active	Well Type	Disposal
Latitude	36.852348	Longitude	-96.503133		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	Raptor Resources, LLC		
Inspect No.		Date Last MIT	08/25/2017	Last Test Result	Acceptable
Casing	5.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	Y	N	Max Pressure 0
FLM Canister Pressure		Actual Pressure	-12	0	Max Volume 45000
Lease Status	Active	Determined?	UIC Staff Gage	Open Value	Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	Y	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	Y	Injection Rate (bpd)	212		
Injecting	Y				
Inspection Comments	At the time of inspection, well OS6222000 was connected and injecting at a rate of 212 barrels per day (BPD) with a cumulative total of 17 barrels displayed on the barrel meter. I observed a tubing pressure of 12 in.Hg vacuum and a casing pressure of 0 psi. The operator should install an accurate, legible well sign displaying the EPA inventory ID number. There were no areas of concern at the time of the inspection.				
Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2022.08.05 16:17:05 -05'00'				
Supervisor Signature	ANTHONY LOSTON Digitally signed by ANTHONY LOSTON DN: c=US, o=U.S. Government, ou=Environmental Protection Agency, cn=ANTHONY LOSTON, 0.9.2342.19200300.100.1.1=68001003655738 Date: 2022.08.09 11:16:17 -05'00'				

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.852348, -96.503133		
City: Foraker	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0666

Orientation: NW

Date of Photo: 08/4/2022

Time of Photo: 12:10 PM

Latitude: 36.852348

Longitude: -96.503133

Photographer: Matthew Allen

Description: This was the Blackland No. 10 well (OS6222000). At the time of inspection, the well was connected and injecting with a rate of 212 barrels per day and displayed a cumulative volume of 17 barrels on the barrel meter. There was no well sign present on the well location. The operator should install an appropriate well sign displaying the EPA inventory ID for the well.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.852348, -96.503133		
City: Foraker	County/Parish: Osage	State: Oklahoma




Photo File Name: DSCN0667

Orientation: NW

Date of Photo: 08/4/2022

Time of Photo: 12:11 PM

Latitude: 36.852348

Longitude: -96.503133

Photographer: Matthew Allen

Description: This was the barrel meter (rate 212 BPD) (total 17 barrels) and tubing pressure gauge (12 in.Hg vacuum) readings which were observed at the time of the inspection.