

FIXED MONITORS - HIGH VALUE REPORT

Floor	Probe	OVER 1 PPM								OVER 3 PPM							
		FRI	SAT	SUN	MON	TUES	WED	THU	TOTAL	FRI	SAT	SUN	MON	TUES	WED	THUR	TOTAL
A	1st Floor South End	7	3	1	4	3	2	2	22	3	0	0	1	0	0	1	5
A	1st Floor North End	8	4	3	8	9	2	7	41	6	1	1	1	1	1	1	12
B	2nd Floor North End	8	7	6	6	9	6	11	53	7	2	4	3	7	2	1	26
B	2nd Floor South End	12	9	12	13	14	11	12	83	7	3	6	9	8	9	1	43
C	3rd Floor South End	46	8	19	18	22	17	21	151	6	3	23	6	1	8	2	49
C	3rd Floor North End	46	35	23	23	31	27	18	303	9	2	28	0	1	2	2	44
	TOTAL	127	66	64	72	88	65	71	553	38	11	62	20	18	22	8	179

BLDG. 1

C	Control Room 3rd Floor	13	29	9	6	13	18	2	90	6	1	11	0	0	1	0	19
	Incoming Bldg. Air	4	0	0	0	1	2	0	7	0	0	8	0	0	0	0	8
	Stairwell	8	2	2	0	4	2	2	20	1	0	1	0	2	0	0	4
	Breathing Air	6	2	2	0	4	0	3	17	3	0	1	0	2	0	1	7

A	1st Floor	6	2	3	1	4	0	0	16	5	0	0	0	0	1	1	7
B	2nd Floor West Side	3	0	1	0	0	0	7	11	0	0	1	0	0	0	1	2
B	2nd Floor East Side	16	1	4	3	0	0	0	34	9	2	9	1	0	3	3	27
C	3rd Floor West Side	1	1	0	2	3	0	1	8	0	1	0	0	3	0	0	4
C	3rd Floor East Side	6	7	10	1	4	1	2	31	7	0	2	5	1	0	0	15
B	Bldg. 115	31	33	0	29	48	11	16	168	0	0	0	1	0	0	2	3
	TOTAL	63	44	18	36	59	12	26	258	21	3	12	7	4	4	7	58

BLDG. 111

C	Control Room 3rd Floor	0	1	0	0	0	0	0	1	0	0	0	0	0	0	0	0
	Incoming Bldg. Air	0	0	7	0	0	0	0	7	0	0	1	0	1	0	0	2
	Breathing Air	0	0	0	0	0	0	0	0	0	0	0	2	0	0	0	2
	Stairwell	1	1	0	3	0	0	1	6	0	0	0	2	0	0	21	23

A	1st Floor West End	3	2	3	3	2	2	1	16	0	1	0	2	1	0	1	5
B	2nd Floor West Side	79	8	2	1	1	6	9	106	2	6	0	0	0	4	2	14
B	2nd Floor East Side	4	2	0	3	8	7	3	27	1	2	0	1	0	6	2	12
C	3rd Floor, West Side	36	71	6	21	46	32	23	235	5	10	1	8	14	19	6	63
C	3rd Floor, East Side	1	0	0	4	0	9	2	16	0	1	0	0	0	1	2	4
A	1st Floor, East Side	0	0	0	2	0	1	1	4	0	1	0	0	0	0	1	2
	TOTAL	123	83	11	34	57	57	39	404	8	21	1	11	15	30	14	100

BLDG. 121

C	Control Rooms	1	0	0	0	1	1	0	4	0	0	0	0	0	0	0	0
	Incoming Bldg. Air	0	0	0	0	0	3	4	7	0	1	0	0	0	0	3	4
	Before B.A. Filter	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1
	After B.A. Filter	0	0	0	0	1	0	2	3	0	1	0	0	0	0	0	1