

Inspection Report
Mechanical Integrity Test
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas TX 75270

Inspector Matthew Allen		MIT Date 08/13/2025		Time 08:30	
Operator Representative Performance Energy Resources, LLC		Report Sent Operator			
Inject Interval 1718 - 1735		USDW 437		Well Type Enhanced Recovery	
Annulus Fluid Type Casing 5.5		Concentric Pkr Tubing 2.875		Packer Depth	
Operator Info Performance Energy Resources, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531		Inventory ID OS5199000			
		API Well No			
		Lease Name S&R			
		Well ID 2-B			
		Location NW 13 25N 11E			
Type of MIT Ada Pressure Test		Test Reason Routine			
Injecting		Injection Rate (bpd)		Tubular Lining	
MIT Due		MIT Freq EVERY FIVE YEARS		Ann Filled (hrs)	
				Ann Press Mont	
Time		Tubing Pressure		Annulus Pressure	
Pre-Test		0			
Initial 08:30		380		Flowback High	
Mid 08:45		380		Mid	
Final 09:00		380		Low	
				End	
				Total Volume	
		ADA Pressure Test - Required Test Pressure (F Fluid Column Ht * Specific Gravity * .433 / N2 Wt Fac = Required Test Pressure)			
				Tubing	Annulus
		Depth to Top Perf/Open Hole		1718	
		Depth to Fluid Level		841	
		Fluid Column Level		877	
		Specific Gravity of Fluid		1.06	
		Nitrogen Weight Factor		1.0614	
		Required Pressure Test		379.240	
		Remedial Action Type			
Fluid Migration Test Type		Remedial Action Type			
Inspection Comments		Well, OS5199000 achieved the calculated test pressure of 380psi and maintained the pressure throughout the required 30-minute observation period. There were no areas of concern at the time of the inspection.			
Inspector Signature		MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2025.09.25 13:52:16 -05'00'			
Supervisor Signature		JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2025.09.26 06:39:15 -05'00'			

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.648457, -96.073542		
City: Barnsdall	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010742

Orientation: W

Date of Photo: 8/13/2025

Time of Photo: 8:39 AM

Latitude: 36.648457

Longitude: -96.073542

Photographer: Matthew Allen

Description: This was well OS5199000 at the time of the inspection.