



**UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 5
77 WEST JACKSON BOULEVARD
CHICAGO, ILLINOIS 60604**

DATE: JUL 25 2019

SUBJECT: CLEAN AIR ACT INSPECTION REPORT
East Side Metals Corporation, Cleveland, Ohio

FROM: Eleanor Kane, Environmental Engineer
AECAB (MI/WI)

THRU: Sarah Marshall, Section Chief
AECAB (MI/WI)

TO: File

BASIC INFORMATION

Facility Name: East Side Metals Corporation

Facility Location: 16800 South Waterloo Road, Cleveland, Ohio

Date of Inspection: June 11, 2019

EPA Inspectors:

1. Eleanor Kane, Environmental Engineer
2. Marie St. Peter, Environmental Engineer

Other Attendees

1. Joe Cornwell, Assistant Manager, East Side Metals Corporation

Contact Email Address: joecornwellesm@gmail.com

Purpose of Inspection: This inspection was part of an initiative to evaluate compliance with refrigerant handling regulations for disposal of small appliances and vehicles in the Cleveland area.

Facility Type: Scrap yard

Regulations Central to Inspection: 40 C.F.R. Part 82, Subpart F

Arrival Time: 8:15am
Departure Time: 8:30am

Inspection Type:

- ☒ Unannounced Inspection
☐ Announced Inspection

OPENING CONFERENCE

- ☒ Credentials Presented
☐ CBI warning to facility provided

The following information was obtained verbally from Mr. Cornwell.

East Side Metals accepts approximately 10 small appliances per week for recycling and disposal. Appliances with cut lines are not accepted. Appliances containing refrigerant are set aside and the contractor Rapid Recovery comes about two times per month to recover the refrigerant. East Side Metals, along with their sister yard West Side Metals, jointly own refrigerant recovery equipment, but that equipment is not currently working.


TOUR INFORMATION

EPA toured the facility: Yes

Data Collected and Observations: Air conditioning units were to the side for refrigerant recovery; no fridges or air conditioning units are accepted from walk-in customers.

Photos and/or Videos: were taken during the inspection.

SIGNATURES

Report Author:  Date: 6/27/19
Section Chief:  Date: 7/25/19

Facility Name: East Side Metals Corporation

Facility Location: 16800 South Waterloo Road, Cleveland, Ohio

Date of Inspection: June 11, 2019

APPENDICES AND ATTACHMENTS

APPENDIX A: DIGITAL IMAGE LOG

1. Photographer Name: Marie St. Peter	2. Date of Inspection: June 11, 2019
3. Company/Facility Name: East Side Metals Corporation	4. Street Address, City, State: 16800 South Waterloo Road, Cleveland, Ohio
5. Number of Images: 1	6. Archival Record Location: C:\Users\ekane\OneDrive - Environmental Protection Agency (EPA)\Cleveland Scrap Initiative\East Side Metals

Image Number	File Name	Date and Time	Description of Image
1	IMG_0751.JPG	2019:06:11 08:14:42	Sign