



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 4
ATLANTA FEDERAL CENTER
61 FORSYTH STREET
ATLANTA, GEORGIA 30303-8960

VIA ELECTRONIC MAIL
CONFIRMATION OF RECEIPT EMAIL REQUESTED

Mr. Brian Ratliff
Environmental Health and Safety Tech
Schaeffler Group USA, Inc.
308 Springhill Farm Road
Fort Mill, SC 29715-9784
ratlibia@schaeffler.com

SUBJ: Resource Conservation and Recovery Act (RCRA) Compliance Evaluation Inspection (CEI)
Schaeffler Group USA, Inc.
EPA ID: SCD049128598

Dear Mr. Ratliff:

On August 19, 2020, the U.S. Environmental Protection Agency, along with the South Carolina Department of Health and Environmental Control (SCDHEC) conducted a CEI at Schaeffler Group USA, Inc. located at 301 Highway 1 South, Cheraw, South Carolina to determine the facility's compliance status with RCRA and applicable regulations.

Enclosed is the EPA RCRA inspection report that indicates deficiencies of RCRA were discovered during the inspection. A copy of this report has been forwarded to the SCDHEC for follow-up and further evaluation in accordance the 2003 Hazardous Waste Civil Enforcement Response Policy.

If you have any questions regarding this matter, please contact Laurie Benton DiGaetano, of my staff, by phone at (404) 562-8948 or by email at benton-digaetano.laurie@epa.gov.

Sincerely,

Alan A. Annicella
Chief
Land, Asbestos and Lead Section
Chemical Safety and Land Enforcement Branch

Enclosure

cc: Tom Richmond, SCDHEC (richmotj@dhec.sc.gov)
Earle Watson, SCDHEC (watsonce@dhec.sc.gov)