

INSPECTION REPORT
Facility Name: Four Way Mufflers & Motors

Attached please find the United States Environmental Protection Agency's (EPA's) inspection report of your inspected facility and/or any vehicles/engines identified therein. EPA is providing this report as a matter of agency policy and will contact you again only if needed.

Without making a determination that your business or organization is a small business, EPA is also providing you with a link to a Small Business Resources Information Sheet (<https://www.epa.gov/compliance/small-business-resources-information-sheet>) which provides an array of resources to help small businesses understand and comply with federal and state environmental laws.

Inspection Information	
Inspection Number:	3601757522-2024
Inspection Date(s):	December 11, 2024
Regulatory Program(s):	Clean Air Act Title II – Mobile Source
EPA Region/Program Conducting Inspection:	Region 4 Air Enforcement Branch
Company Name:	Fourway M & M LLC
Facility Name:	Four Way Mufflers & Motors
Facility Street Address:	1368 East Broadway
Facility City, State, Zip Code:	Gallatin, Tennessee 37066

Inspection Report Revision History		
Revision #	Revision Date	Reason for Revision

Inspector and Supervisor Approval			
<u>Carrie Griffith</u> Field Inspector Name	<u>CARRIE GRIFFITH</u> Field Inspector Signature	 Digitally signed by CARRIE GRIFFITH Date: 2025.02.11 07:39:41 -05'00'	_____ Date
<u>Todd Groendyke</u> Name of Approving Official	<u>Chief, SAES</u> Title	<u>TODD GROENDYKE</u> Approving Official Signature	 Digitally signed by TODD GROENDYKE Date: 2025.02.11 09:14:30 -05'00'

INSPECTION REPORT

Facility Name: Four Way Mufflers & Motors

General Inspection Information			
Inspector(s):	Carrie Griffith, Lorianny Rivera	Arrival Date/Time:	12/11/2024 9:18 CST
Primary Facility Representative & Title:	Shawn Fennell, Owner	Departure Date/Time:	12/11/2024 12:20 CST
Facility Contact Phone/Email:	615-426-7113 fourwaymufflers@gmail.com	Compliance Assistance Reference Materials Provided to Facility:	☒ SBREFA Form ☒ EPA Enforcement Alert ☐ EPA Tampering Policy ☐ Copy of CAA § 203(a)(3) ☐ Copy of CAA § 114 ☐ §208/§114 Preservation Letter ☒ Discussion of Right to Claim CBI ☐ Other:
Time Inspector(s) Presented Credentials:	9:30 CST		
Permission to Enter Facility Granted? If Yes, by whom? If No, explain.	Yes – Shawn Fennell, Owner, consented to the inspection during the opening meeting		
Photograph Range:	0023 - 0053	Photographer Name:	Griffith
Notes:	Four Way M&M is wholly owned by Shawn Fennell and Vicki Fennell. The company began as a used car dealership in the 1970s and added a service shop in 1984. The business has only one location.		

Facility Business Activities			
Type(s) of Services (check all that apply)		Description/Observations (types and brands of parts that are manufactured or sold, types of shop services provided, etc.)	Estimated Throughput (e.g., sales per month, installs per week)
☐	Manufacturing		
☐	Retail		
☒	Service Shop	The shop provides all kinds of service for all kinds of vehicles, but the majority of work is done on gasoline passenger cars. Facility personnel stated that they do not do ECM programming or tuning.	Approx. 40-80 vehicles serviced per week
☐	Fleet		
☒	Other	The company purchases and resells used trucks. Approximately 90% of inventory is purchased at auction.	Approx. 3-7 trucks sold per month
Notes			

INSPECTION REPORT

Facility Name: Four Way Mufflers & Motors

Personnel Interviewed			
Name	Title	Contact Info. (e.g., email, phone number)	Interviewed by (Last name of Inspector)
Shawn Fennell	Owner	615-426-7113 patrickshawnfennell@gmail.com	Griffith
Zach Fennell	Vice President	615-426-2012	Griffith
Vicki Fennell	Owner	n/a	Rivera

Documents Requested		
Document Requested	Status	Notes/Comments
Records of all vehicles sold from June 2024 to December 2024.	☒ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	Inspector Griffith reviewed physical records on site.
Work orders/invoices for all service performed from June 2024 to December 2024.	☒ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	Inspector Rivera reviewed electronic records on site.
Purchase records for trucks inspected.	☒ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	Inspectors took hard copies of the bill of sale and invoice for the two inspected trucks listed below.
	☐ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	
	☐ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	

Vehicles Inspected/Observed				
VIN (last 8 digits)	EPA Engine Family	Appearance of Tampering (Yes/No/TBD)	OBD Scan Conducted? (Yes/No)	Observations
HG711449	HCRX2V0CV067	Yes	Yes	Inspectors observed a straight pipe installed.
HEB75228	HFMXD06.761B	Yes	Yes	Inspectors observed a straight pipe installed.

PHOTOGRAPH LOG**Four Way Mufflers & Motors**

Image Number	File Name	Date	Time (CST)	Description of Image
1	PC110023.JPG	12/11/2024	10:24	Vehicle 1 – front
2	PC110024.JPG	12/11/2024	10:25	Vehicle 1 – rear
3	PC110025.JPG	12/11/2024	10:25	Vehicle 1 – engine
4	PC110026.JPG	12/11/2024	10:25	Vehicle 1 – label
5	PC110027.JPG	12/11/2024	10:25	Vehicle 1 – label
6	PC110028.JPG	12/11/2024	10:26	Vehicle 1 – label
7	PC110029.JPG	12/11/2024	10:26	Vehicle 1 – label
8	PC110030.JPG	12/11/2024	10:26	Vehicle 1 – side
9	PC110031.JPG	12/11/2024	10:26	Vehicle 1 – dashboard
10	PC110032.JPG	12/11/2024	10:26	Vehicle 1 – dashboard
11	PC110033.JPG	12/11/2024	10:27	Vehicle 1 – dashboard
12	PC110034.JPG	12/11/2024	10:28	Vehicle 1 – exhaust
13	PC110035.JPG	12/11/2024	10:28	Vehicle 1 – exhaust
14	PC110036.JPG	12/11/2024	10:28	Vehicle 1 – exhaust
15	PC110037.JPG	12/11/2024	10:39	Ground
16	PC110038.JPG	12/11/2024	10:39	Vehicle 2 – front
17	PC110039.JPG	12/11/2024	10:39	Vehicle 2 – side
18	PC110040.JPG	12/11/2024	10:39	Vehicle 2 – rear
19	PC110041.JPG	12/11/2024	10:39	Vehicle 2 – exhaust
20	PC110042.JPG	12/11/2024	10:39	Vehicle 2 – exhaust
21	PC110043.JPG	12/11/2024	10:39	Vehicle 2 – exhaust
22	PC110044.JPG	12/11/2024	10:47	Vehicle 2 – label
23	PC110045.JPG	12/11/2024	10:48	Vehicle 2 – dashboard
24	PC110046.JPG	12/11/2024	10:50	Vehicle 2 – label
25	PC110047.JPG	12/11/2024	10:50	Vehicle 2 – engine
26	PC110048.JPG	12/11/2024	10:51	Vehicle 2 – engine
27	PC110049.JPG	12/11/2024	10:51	Vehicle 2 – engine
28	PC110050.JPG	12/11/2024	10:53	Vehicle 2 – dashboard VIN (unclear)
29	PC110051.JPG	12/11/2024	10:53	Vehicle 2 – dashboard VIN (unclear)
30	PC110052.JPG	12/11/2024	10:54	Vehicle 2 – dashboard VIN
31	PC110053.JPG	12/11/2024	10:54	Vehicle 2 – dashboard VIN

Photographs were taken by EPA inspector Carrie Griffith.