

ELECTRON MICROSCOPE PHOTOGRAPHS

FIGURE NO. 9
Asbestos fiber from new brake lining
5000x




FIGURE NO. 10
New brake lining scrapings after
heating to 1200°F. for 30 minutes
5000x

All fibers in Figures No. 10, 11 and 12 are below 5 micron in length.




FIGURE NO. 11
Debris from dry brake compartment
5000x




FIGURE NO. 12
Debris from dry brake compartment
5000x

35 Microns - Thickness of a human hair at 5000x