

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	I	N	S	P	E	C	T	0	0	1
Year-Month-Day:					2	0	2	4	-	1	0	-	2	4	
EPA Permit # (or RA):															
						Page			1	Of			2		
Inspector(s): Carol Chen (lead), Lonnie Dorn Start Time: 8:55 am															
End Time: 8:59 am															
Facility Contact Information	Facility Name: Logsdon Valley Oil Co., Inc.														
	Street Address: 105 Bedford Court														
	City: Horse Cave County: Barren State: KY Zip: 42749														
	Nature of Business: oil production														
	Facility Owner/Operator: Ms. Ellen Stinson, President Phone: 270-537-4288														
	Email: estinson@scrtc.com														
	Facility Contact (if different): Phone:														
	O/O Mailing Address: 105 Bedford Court														
Well Data from File	City: Horse Cave County: Barren State: KY Zip: 42749														
	Well Name & #: BILLY JOE CAUDEL #UIC-1														
	Well Type (see table): Class II-D, Produced Water Disposal State Permit: 111143														
	Latitude (°N): 37.159722 Longitude (°W): -85.79625 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	☐ Other: 7" surface casing, 8 7/8" hole														
	Total Depth (ft): 349' Inner Casing Size (in): 4 1/2" Tubing Size (in): 2 3/8" Packer Depth (ft): 650														
Field Measurements and Observations	Inj. Zone: ☒ Open Hole; ☐ Perforated; Top(ft) Bottom(ft): Max. Injection Pressure (psig):														
	Latitude (°N): 000 Longitude (°W): 000 Elevation (ft):														
	EPA GPS ID: SC8284 Well Status (see table): TA If not Active, Reported Date Last Active: 7/30/2019														
	Nature of Injected Fluid(s) if any:														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values):														
	The injection well is disconnected and shows some corrosion. No injection line is onsite.														
	The storage tank is beside the injection well and does not have any disposal piping attached.														
See reverse for additional observations, comments and photo log															
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN								Signature:							
Digitally signed by CAROL CHEN Date: 2024.12.10 17:20:09 -05'00'															
Version 2018-04-18															

Inspection ID	EPA Well ID#:	I	N	S	P	E	C	T	0	0	1
	Year-Month-Day:	2	0	2	4	-	1	0	-	2	4
	EPA Permit # (or RA):										
						Page	2	Of	2		

[illegible]

Photographer: Carol Chen EPA Camera ID: SC8284

Photo ID: DSCN1512 Time: 8:55 am Lat (°N): 000 Long (°W): 000

Description: injection well

Photo ID: DSCN1513 Time: 8:55 am Lat (°N): 000 Long (°W): 000

Description: storage tank

Photo ID: DSCN1514 Time: 8:56 am Lat (°N): 000 Long (°W): 000

Description: storage tank

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

UIC Inspector
Name: _____
Signature: _____