

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	12/12/2019	
Media Program:	Water	
Regulatory Program(s)	Brine - SDWA	
Company Name:	Unknown	
Facility Name:	Unknown (Bird Creek)	
Facility Physical Location:	36.8325, -96.4999	
(city, state, zip code)	Pawhuska, Oklahoma 74056	
Mailing address:	Unknown	
(city, state, zip code)	Unknown	
County/Parish:	Osage County	
Facility Phone Number	Unknown	
Facility Contact:	Unknown	
	Unknown	
FRS Number:	N/A	
Identification/Permit Number:	N/A	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		7 JAN 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Unknown oil and gas facility located at latitude 36.8325 and longitude -96.4999 near Pawhuska, Oklahoma on 12/12/2019 for an unannounced inspection. There were no representatives of the facility present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

EPA conducted an observation and inspection of surface monitoring, as required, in the North Bird Creek area of concern. Mr. Bert Fisher, a representative of the operators in this area of concern was on site with me during the observation.

Section II - OBSERVATIONS

I witnessed company representative, Mr. Bert Fisher, take initial readings of Total Dissolved Solids (TDS) at previous EPA monitoring stations 2 and 6. Mr. Fisher documented his field readings, equipment QA/QC processes, and other information as needed. The TDS reading at the previous EPA monitoring station number 2 measured 430 milligrams per liter (mg/L) at 5.5 degrees Celsius. A TDS reading at the previous EPA monitoring station number 6 measured 423 mg/L at 4.8 degrees Celsius. I observed that the water appeared murky at these locations and was flowing slightly.

Section III – AREAS OF CONCERN

N/A

Section IV – FOLLOW UP

EPA will conduct follow up inspections as determined appropriate.

Section V – LIST OF APPENDICES

N/A