

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	12/14/2023	Time	12:15
Inspection Due	2018-02-07T00:00:00Z	Operator Representative	2020 Harris Partners, LLC		
Operator Info	2020 Harris Partners, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531	Inventory ID	OS2326000		
		API Well No			
		Lease Name	JUMAS		
		Well ID	W-11		
Location	NE 16 25N 12E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.644123	Longitude	-96.009864		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	2020 Harris Partners, LLC		
Inspect No.		Date Last MIT		Last Test Result	
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 436
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed well OS2326000 (Jumas W-11). The casing was open to the atmosphere, and the tubing was closed by a gate valve. The tubing was bent over, it appeared to have been hit by a vehicle. Inspector was unable to obtain a fluid level at the time of the inspection due to poor and improper well maintenance.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.644123, -96.009864		
City: Bartlesville	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010249

Orientation: NNE

Date of Photo: 12/14/2023

Time of Photo: 12:11 PM

Latitude: 36.64413

Longitude: -96.00989

Photographer: Matthew Allen

Description: This was well OS2326000 and its well sign at the time of the inspection.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.644123, -96.009864		
City: Bartlesville	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010250

Orientation: NE

Date of Photo: 12/14/2023

Time of Photo: 12:11 PM

Latitude: 36.64414

Longitude: -96.00988

Photographer: Matthew Allen

Description: This was well OS2326000 at the time of the inspection. The casing was open to the atmosphere and the tubing was damaged.