

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	K	Y	S	1	5	3	0	1	6	8
Year-Month-Day:					2	0	2	4	-	1	0	-	2	2	
EPA Permit # (or RA):					R	A									
					Page	1		Of	2						
Inspector(s): Carol Chen (lead), Lonnie Dorn Start Time: 9:35 am															
End Time: 9:36 am															
Facility Contact Information	Facility Name: Slone Energy, LLC														
	Street Address: 8966 KY RT 40 West, P.O. Box 220														
	City: Oil Springs County: Magoffin State: KY Zip: 41238														
	Nature of Business: oil production														
	Facility Owner/Operator: Mr. S. Chris Slone, PE Phone: 606.297.5330 work														
	Email: chrisslone@sloneenergy.com														
	Facility Contact (if different): Phone: 606.225.2206 cell														
	O/O Mailing Address:														
	City: County: State: Zip:														
Well Data from File	Well Name & #: R. L. SALYERS - JIM ARNETT #W-2														
	Well Type (see table): Class II-R, Enhanced Oil Recovery (EOR) State Permit:														
	Latitude (°N): 37.70643 Longitude (°W): -83.01572 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	☐ Other: 4 1/2" production casing														
	Total Depth (ft): Inner Casing Size (in): 2 3/8" Tubing Size (in): 1" Packer Depth (ft):														
Field Measurements and Observations	Inj. Zone: ☐ Open Hole; ☐ Perforated; Top(ft) Bottom(ft): Max. Injection Pressure (psig):														
	Latitude (°N): 000 Longitude (°W): 000 Elevation (ft):														
	EPA GPS ID: S75332 Well Status (see table): TA If not Active, Reported Date Last Active: 7/07/2010														
	Nature of Injected Fluid(s) if any:														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values):														
	The injection line from the tank battery is not connected to the injection well. This well is inactive.														
	The wellcap shows corrosion.														
See reverse for additional observations, comments and photo log															
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN								Signature:							
Digitally signed by CAROL CHEN Date: 2024.12.11 11:15:56 -05'00'								Version 2018-04-18							

Inspection ID	EPA Well ID#:	K	Y	S	1	5	3	0	1	6	8
	Year-Month-Day:	2	0	2	4	-	1	0	-	2	2
	EPA Permit # (or RA):	R	A								
					Page	2		Of	2		

(Cont)

R. L. SALYERS - JIM ARNETT #W-2

Photographer: Carol Chen EPA Camera ID: S75332

Photo ID: RIMG0181 Time: 9:36 am Lat (°N): 000 Long (°W): 000

Description: view of the injection well

Photo ID: RIMG0182 Time: 9:36 am Lat (°N): 000 Long (°W): 000

Description: close-up of the injection well

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W): _____

Description: _____

UIC Inspector

Name: _____

Signature: _____