

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#: F L S 1 1 3 0 0 2 2											
						Year-Month-Day: 2 0 2 4 - 0 4 - 3 0											
						EPA Permit # (or RA):											
						Page 1 Of 2											
Inspector(s): Carol Chen (lead), Carla Foy Start Time: 2:43 pm																	
End Time: 2:44 pm																	
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC (Breitburn Operating, LP)																
	Street Address: 5415 Oil Plant Rd																
	City: Jay County: Santa Rosa State: FL Zip: 32565																
	Nature of Business: oil and gas production																
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702																
	Email:																
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319																
	O/O Mailing Address: 5415 Oil Plant Rd																
Well Data from File	City: Jay County: Santa Rosa State: FL Zip: 32565																
	Well Name & #: J. F. SHELL #20-1 API No. 0911320019 PA No. 311579																
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: OG_483																
	Latitude (°N): 30.951882 Longitude (°W): -87.175408 Elevation (ft):																
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing																
	PBTD: 15902' ☐ Other: surface casing 10 3/4" at 3748'																
	Total Depth (ft): 15993' Inner Casing Size (in): 7" 15993 Tubing Size (in): 3 1/2" 15480' Packer Depth (ft): 15354'																
	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) 15600' Bottom(ft): 15750' Max. Injection Pressure (psig): 7500 N2 gas 4400psi PW																
Field Measurements and Observations	Latitude (°N): Longitude (°W): Elevation (ft):																
	EPA GPS ID: Well Status (see table): PA If not Active, Reported Date Last Active:																
	Nature of Injected Fluid(s) if any:																
	General Condition of the Well Site:																
	Notes & Comments (include discrepancies from database values):																
	The inspectors were informed this well was plugged, but																
	we did not stop to see the lease at that time, just drove																
	past the general area.																
	Tubing gauge:																
	Production gauge:																
Surface gauge:																	
Flow line gauge:																	
See reverse for additional observations, comments and photo log																	
UIC Inspector								UIC Inspector									
Name: Carol Chen								Name:									
Signature: CAROL CHEN								Signature:									
Digitally signed by CAROL CHEN Date: 2024.06.20 21:26:55 -04'00'																	
Version 2018-04-18																	

[illegible]

(Cont)

J. F. Shell #20-1	State Permit No. OG_483	API No. 0911320019
No photos taken		

Photographer: **Carol Chen** EPA Camera ID: **S75332**

Photo ID: **No photos taken** Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

UIC Inspector

Name: _____

Signature: _____