Applied Environmental Services
"Consultants in Wastes Management and Environmental Control"
ASBESTOS MGMT • AIR POLLUTION STUDIES • HAZARDOUS WASTE/RCRA COMPLIANCE • ENVIRONMENTAL AUDITS
4100 RIO BRAVO SUITE 320 EL PASO, TEXAS 79902 (915) 533-4108

PLAINTIFF'S EXHIBIT
CHV-794

29 December 1987

Rafael Nickolas, Jr. President
Applied Environmental Services
716 La Cruz
El Paso, Texas 79902

Dear Mr. Nickolas:

The following sample were run for asbestos using method NIOSH 7400A:

Sample No.	Time-m	Flow-l	Fibers/cc
S-56, area I, c-pipeway area, removal	300	15	<0.01
S-57, area I, c-pipeway personal, removal	300	2	<0.01
S-58, area I, c-pipeway area, removal	330	15	<0.01
S-59, area I, c-pipeway personal, removal	330	2	<0.01

Sincerely,

Howard G. Applegate
Ph.D.

AES
Applied Environmental Services
4100 Rio Bravo Suite 320
El Paso, Texas 79902

CLIENT: DARLA ENVIRONMENTAL

PROJECT: CHEVRON

DATE: december 28, 1987

ANALYZED BY: DR. HOWARD APPLEGATE

DATE: DECE,BER 29, 1987

Chevron BB
015579

SAMPLE NO.	S-56	S-57	S-58	S-59				
SAMPLE LOCATION	AREA I "C" PIPEWAY REMOVAL AREA SAMPLE	AREA I "C" PIPEWAY REMOVAL PERSONAL SAMPLE	AREA I "C" PIPEWAY REMOVAL AREA SAMPLE	AREA I "C" PIPEWAY REMOVAL PERSONAL SAMPLE				
FILTER SIZE (mm)	25	25	25	25				
START TIME	8:45 am	8:48 am	8:50 am	8:56 am				
END TIME	1:45 pm	1:48 pm	2:20 pm	2:26 pm				
RATE OF FLOW (lpm)	15	2	15	2				
TOTAL TIME (hrs)	5	5	5.5	5.5				
VOLUME SAMPLED (l)	4500	600	4950	660				
RESULTS (f/cc)	$<$0.01	$<$0.01	$<$0.01	$<$0.01				