

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	1/29/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	T Bar M Energy Resources, LLC	
Facility Name:	Tom Burrow Lease	
Facility Physical Location:	35.8099, -96.104067	
(city, state, zip code)	Beggs, Oklahoma 74070	
Mailing address:	1302 Commercial	
(city, state, zip code)	Mounds, Oklahoma 74047	
County/Parish:	Okmulgee County	
Facility Phone Number	(918) 827-3174	
Facility Contact:	Travis Allen	
	TBARMENERGY@gmail.com	
FRS Number:	N/A	
Identification/Permit Number:	N/A	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		28 FEB 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the T Bar M Energy Resources, LLC oil and gas facility located near Beggs, Oklahoma on 01/29/2020 for an unannounced inspection. There were no representatives of T Bar M Energy Resources, LLC present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

The facility is known as the Tom Burrow Lease.

Section II - OBSERVATIONS

During the inspection, I observed the tank battery with no secondary containment and there was a cut in the berm wall at the facility. I observed runoff flowed towards a pond, which was not affected at the time of the inspection. During the inspection, the separator leaked from the base was corroded. The leaking fluids flowed from the battery towards the nearby pond. I observed some surface damage near the tank battery outside of the secondary containment area.

Section III – AREAS OF CONCERN

There was a leaking separator and no secondary containment to prevent flow from the site towards a nearby pond.

Section IV – FOLLOW UP

EPA water enforcement will refer this facility to EPA R6 SPCC program.

Section V – LIST OF APPENDICES

N/A