

Leak Detection and Elimination Sheet

ABD00147862

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repa: Verify: By:
14:35	4901	#3		Dump tank			Flush tank		Jeff	
8-10-01	4902	#9	6.1	LOMO R.S.			Steamer Suedo Closed Control Valve		Sykes	
8-10-01	4902	#3		K.O. tank pumps			Flushed seals		Rodney Strickland	
14:42	4903	#5	10.3	IS					Jeff Sykes	
8-10-01	4903	GC 3	5.2	Dump Tank (LOMO)			Flushed tank Closed control valve		Jeff Sykes	
15:20	CN	#10,7	8.3	IS			Steamer Suedo			
8-10-01	4904	GC#1 #3	6.3				Nothing	8-10	DB	DB
18:05	GS						Found			
8-10-01	4905	GC1 1	6.9	#3 Compum	150		Isolated #3 compum valued off compum			
19:00	GS	1	10							
8-10-01	4906	GC#1 3	10.5	#3 compum			Isolated #3 comp valued off compum			
21:15	GS									

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.
This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.

Leak Detection and Elimination Sheet

ABD00147863

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verifier By:
8-7-01	4895	#1	7.4/9.5	VCM Railcar unloading C.S.	0	NO	nothing found waiting for JMC			CO
0130	OK	#1	5.9/8.0							
8-9-01	4896	GC5	5.7			NO	FOUND NOTHING			
0615	CN	#2		05	0					
8-9-01	4897	#1			D	NO	Closed manual valve	8-9	DB	DB
1300	TS	#4	7.7	DB	D					
8-9-01	4898	#1			D	NO	nothing Found	8-9	DB	DB
18:00	TS	#3	5.5	DB						
8-10-01	4899	#1			0	NO	Pulled shut down	8-10	FP	FP
06:50	TS	#1	6.5	7P						
8-10-01	4900	#1			10	NO	Pulled pot down on #4 comp.	8-10	TC	TC
14:15	TS	#1	7.8	TC						

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.
This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.