

Class I and II Well Inspection Form
US Environmental Protection Agency – Region 4
Underground Injection Control Program
61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303
Phone: (404)562-9424

Inspection ID

EPA Well ID#:	F	L	S	1	1	3	0	0	1	0
Year-Month-Day:	2	0	2	2	–	0	9	–	1	3
EPA Permit # (or RA):							7	2	8	
Page	1	Of	2							

Inspector(s): Jason Rose _____ (lead), Page Cirillo _____ Start Time: 10:40 AM _____
_____ End Time: 10:52 AM _____

Facility Contact Information

Facility Name: *Blackjack Plant* _____
Street Address: *4940 Blackjack Plant Road* _____
City: *Jay* _____ County: *Santa Rosa* _____ State: *FL* _____ Zip: *32535* _____
Nature of Business: *Oil and gas production* _____
Facility Owner/Operator: *Black Creek Energy, LLC* _____ Phone: *(601) 431-5386* _____
Email: *harris.butler@butlerroyals.com* _____
Facility Contact (if different): *Michael Wetzel* _____ Phone: *(850) 324-6271* _____
O/O Mailing Address: *140 Virginia Street, Suite 402* _____
City: *Richmond* _____ County: *NA* _____ State: *VA* _____ Zip: *23209* _____

Well Data from File

Well Name & #: *W.W. Foskett #25-N* _____
Well Type (see table): *Enhanced Recovery (EOR)* _____ State Permit: API # *0911320136* _____
Latitude (°N): *30.833716°N* _____ Longitude (°W): *-87.0953°W* _____ Elevation (ft): *NA* _____
Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing

PBTB 16,018'

☐ Other: _____
Total Depth (ft): *16,120'* _____ Inner Casing Size (in): *7"* _____ Tubing Size (in): *3.5"* _____ Packer Depth (ft): *15,700'* _____
Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft): *15,958'* Bottom(ft): *15,992'* _____ Max. Injection Pressure (psig): *2,500 psi* _____

Field Measurements and Observations

Latitude (°N): *30.833734°N* _____ Longitude (°W): *-87.095360°W* _____ Elevation (ft): *NA* _____
EPA GPS ID: PG No. *3358766066* _____ Well Status (see table): *AC* _____ If not Active, Reported Date Last Active: _____
Nature of Injected Fluid(s) if any: _____
General Condition of the Well Site: The site is clean and well maintained. There was no evidence of leaks or excessive _____
corrosion. The access stairs are not stable, could use some repairs/upgrades to ensure safety of personnel. _____
Notes & Comments (include discrepancies from database values): _____
The internal pressure gauge was reading 1,750 psi. The surface casing pressure gauge was reading 80 psi. The operator suggested that this is likely due to the thermal expansion of the fluids above the top of cement due to having been shut in for a long period, then being recently reactivated. The operator indicated this is not indicative of an MI issue, because the production casing pressure still reads 0 psi.
Perfs (see well schematics):
4 SPF 15958-66' GRM (1974-08) & 15966-92' added (1976-07)

See reverse for additional observations, comments and photo log

Owner/Operator Representative (Optional)

Name: *Cliff Emmons* _____
Signature & Date: *see attached field notes* _____

UIC Inspector

Name: *Jason Rose* _____
Signature & Date: *Jason Rose* *10/26/22* _____

Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	1	0
	Year-Month-Day:	2	0	2	2	–	0	9	–	1	3
	EPA Permit # (or RA):							7	2	8	
					Page		2	Of		2	

[illegible]

Photographer: Jason Rose _____ EPA Camera ID: PG camera ID no. 14 S/N:31029537 _____

Photo ID: 1 _____ Time: 10:41 AM ____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking south, W.W. Foskett #25-N sign alongside access road.* _____

Photo ID: 2 _____ Time: 10:48 AM ____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking north, site overview, showing well head, pressure gauges, valves, and access stairs.* _____

Photo ID: 3 _____ Time: 10:49 AM ____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking west, closeup view of surface pressure gauge reading 0 psi.* _____

Photo ID: 4 _____ Time: 10:49 AM ____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking north, closeup view of production casing pressure gauge reading 0 psi.* _____

Photo ID: 5 _____ Time: 10:49 AM ____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking south, view of incoming line pressure gauge reading 1,520 psi.* _____

Photo ID: 6 _____ Time: 10:50 AM ____ Lat (°N): NA _____ Long (°W): NA _____

Description: *Looking west, view of internal presure gauge reading 1,750 psi.* _____

UIC Inspector

Name: Jason Rose _____

Signature & Date: Jason Rose 10/26/22

Site Photographs
W.W. Foskett #25-N:
September 13, 2022



Photograph 1: Looking south, W.W. Foskett #25-N sign alongside access road.



Photograph 2: Looking north, site overview, showing well head, pressure gauges, valves, and access stairs.



Photograph 3: Looking west, closeup view of surface pressure gauge reading 80 psi.



Photograph 4: Looking north, closeup view of production casing pressure gauge reading 0 psi.



Photograph 5: Looking south, view of incoming line pressure gauge reading 1,520 psi.



Photograph 6: Looking west, view of internal pressure gauge reading 1,750 psi.