

INTEROFFICE CORRESPONDENCE

PLAINTIFF'S EXHIBIT

MBL-273

DATE: March 13, 1988

TO: J. M. Murrin
P. E. Eubanks
J. L. Willis
V. S. Soares

CC: T. A. Monzitta

PLANT ASBESTOS AREAS

We have received the results of the samples sent out recently for asbestos tests.

The attached is a list of locations in the plant which the tests indicate have asbestos present in the insulation.

Also attached are copies of the Lab Test results. NOTE: This does not include areas previously shown to have asbestos such as Calciner Furnaces and Dowtherm.

L. K. Reno
L. K. Reno

LKR/sf
0244Y

014276

SAMPLE

LOCATION

1	One inch line in North end of Building #1
2	Pump discharge line on old Dowtherm Unit, east side
19	H-302 outlet line
22	8: Steam line across Neches Street at valve
23	8" Steam line at P.5, 824
24	8" Steam line at P.5, 834
25	Steam line to Cooling Tower from East/West pipe rack
29	Tracing steam line to P-407 waste pump
30	H-402 sight glass insulation
31	Low pressure steam line to T-401, 402, 206 and 207
33	150 pound steam line to Acrylics
34	Low pressure steam line to Acrylics
35	Two inch steam line to 2nd floor of #1 Building
37	Four inch steam line to Catalyst Unit
45	V-252 insulation at east end
46	V-253 insulation at east end
47	P-251 Discharge line
48	V-248 insulation - south side
49	V-246 insulation
53	P-254 Discharge Manifold
54	P-247 to V-248 line
55	P-247 to V-252 line
57	P-247 to V-253 line
58	P-257 to T-402 line
59	P-253 to T401 line

014277

64	P-248 to V-248 line
65	Steam line to E-443 loading racks
66	Steam tracing line at E-443 loading racks
67	Steam tracing line to V-246
68	Steam line to P-259 (tempered loop)
69	V-221 insulation
72	P-253 discharge to suction line
81	Steam line at A-1 loading rack (North/South Tank Car Rack)
82	P-176 Discharge line, at kA-1 spot
83	Open four inch line at B-2 spot, tank car rack
85	One inch steam line at A-2 spot, tank car rack
88	Four inch line to loading at east side of crossing
89	Four inch line to loading rack at east side of crossing
97	One inch steam line, southwest of V-250, below deck
101	Four inch steam line to E-126
103	Three inch line south of V-250, 2nd floor
104	Steam Line south of V-237, 2nd floor
105	Six inch low pressure steam line south of V-237, 2nd floor pipe rack
110	Composite sample from lay down yard

LKR/sf
0244Y

014278