

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	02/16/2023	Time	12:00
Inspection Due	2021-12-10T00:00:00Z	Operator Representative	Contango Resources, LLC		
Operator Info	Contango Resources, LLC 1717 South Boulder, Suite 900 Tulsa, OK 74119 Phone: 918-392-3396	Inventory ID	OS6106000		
		API Well No			
		Lease Name	PETERS		
		Well ID	10-B		
Location	NE 04 22N 12E	Status	Active	Well Type	Enhanced Recovery
Latitude	36.413704	Longitude	-96.020576		
Inspection Reason	MIT		Responsible Company at Time of Inspection	Contango Resources	
Inspect No.		Date Last MIT	12/11/2019	Last Test Result	Acceptable
Casing	4.5	Tubing	2.375	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 300
FLM Canister Pressure		Actual Pressure	0	190	Max Volume 12000
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector witnessed Standard Annulus Pressure Test (SAPT) on well OS6106000. Pressure, hold OK. I observed no areas of concern at the time of the inspection. EPA enforcement staff will review inspection data to determine compliance with EPA UIC regulations. Post Workover MIT Replaced tubing from steel to plastic lined steel, replaced standard packer with nickel plated packer. Initial: 205psi Mid: 205psi Final: 205psi Pressure Hold OK Total flowback: 2400ml Packer Depth: 1433'				
Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2023.03.15 12:24:52 -05'00'				
Supervisor Signature	DAMON MCELROY Digitally signed by DAMON MCELROY DN: c=US, o=U.S. Government, ou=Environmental Protection Agency, cn=DAMON MCELROY, 0.9.2342.19200300.100.1.1=68001003655653 Date: 2023.03.17 17:18:51 -05'00'				

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.413704, -96.020576		
City: Skiatook	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010083

Orientation: NE

Date of Photo: 02/16/2023

Time of Photo: 12:07 PM

Latitude: 36.413704

Longitude: -96.020576

Photographer: Matthew Allen

Description: This was well OS6106000 at the time of the inspection.